

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville IN
US
47725
812-867-5200

WORK ORDER # 66669

Completed : 17 MAR 22
Licence # :
Stock No : 10958
Tag :
Author : BJW
Location : 0323 SEE IF PARTS A
Serial# : 4YDF29029M2512373
Warr. Date : 17 JUL 21
Print Date : 17 MAR 22
Customer : 1013 - KEYSTONE RV CO -
Invoice # :
Description : 2021 5W KEYSTONE COUGAR 290RLS
Date In : 04 MAR 22 Mileage : 0
Promised : 25 MAR 22
Date Sched :
Chassis# : 4YDF29029M2512373
Cust PO# :

Job # Description JOB INFORMATION Type Bill To

1 COMPLAINT: CUSTOMER STATES THAT THE HEAT AND I SPN SALES
VIBRATION IS NOT WORKING IN THE RECLINER
CORRECTION: THE DOUBLE RECLINER DOES WORK ON HEAT
AND VIBRATION SAT IN EACH ONE
2 COMPLAINT: CUSTOMER STATES THAT THE GRAY TANK LEVEL I SPN SALES
READS 3/4 TANK REGARDLESS OF HOW MUCH IS
IN IT
CORRECTION: TOOK PICTURES ALL TANKS ARE EMPTY EVEN
THE GREY TANK
3 COMPLAINT: INSERT MOLDING COMING OFF ON FRONT W 1013 KEYST
OVERHANG
CORRECTION: REMOVED THE SCREW AND ADJUSTED THE
INSERT PUT IT BACK IN TRIM PUT SCREW
BACK IN
4 COMPLAINT: LOCK ON DOORSIDE FRONT COMP LOCK FLAPPER W 1013 KEYST
STUCK AND KEY WOULD NOT GO IN
CORRECTION: PUT IN A PO FOR NEW LATCH AND LOCK
5 COMPLAINT: GUTTER SPOUT OFF W 1013 KEYST
CORRECTION: REMOVED SCREWS THERE WAS NO BROKEN
PIECES OF A GUTTER SPOUT. MAYBE IT WAS
JUST SILICONED ON. PUT A NEW GUTTER
SPOUT ON PUT SCREWS BACK IN TOUCHED UP
WITH SILICONE
6 COMPLAINT: CHECK LEVELING SYSTEM I SPN SALES
CORRECTION: RAN AUTO LEVELING SYSTEM TWICE HAD
SUCCESS BOTH TIMES

Job # Part No Description PARTS Bill to Qty Price Total

4 672831 Door - Baggage - A W-1013 1 18.03 18.03
5 5569 94174 BLK LONG RAIN GUTTER SP W-1013 1 5.61 5.61

Continued on page 2

Work Order : 66669

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
1 Z990  MISCELLANEOUS REPAIR  SAR  I-SPN  0.50  25.00  12.50
2 Z990  MISCELLANEOUS REPAIR  SAR  I-SPN  0.20  25.00  5.00
3 Z990  MISCELLANEOUS REPAIR  SAR  W-1013  0.30  150.00  45.00
4 Z990  MISCELLANEOUS REPAIR  SAR  W-1013  0.00  150.00  0.00
4 Z990  MISCELLANEOUS REPAIR  SAR  W-1013  0.20  150.00  30.00
4 Z990  MISCELLANEOUS REPAIR  SAR  W-1013  0.00  150.00  0.00
5 Z990  MISCELLANEOUS REPAIR  SAR  W-1013  0.20  150.00  30.00
6 Z990  MISCELLANEOUS REPAIR  SAR  I-SPN  0.20  25.00  5.00
*****

```

```

*****
Job #  Excode  Description  EXTRAS  bill to  Qty  Price  Total
*****
1  SS  SHOP SUPPLIES  I-SPN  1.00  0.00  0.00
4  FRT  UPS-LOCK  W-1013  1.00  11.76  11.76
*****

```

CUSTOMER COMMENTS

```

*****
LOCK ARRIVED IN BACKROOM 3-15-22...CAM
BH GAVE PARTS SHEET TO MATT
BH SENT IN PREAUTH
CHANGED BILL TYPE BECAUSE NOT COVERED
*****

```

BILLINGS SUMMARY

```

*****
Type Bill Id  Parts  Labour  Sublet  Extras  Tax  Total
*****
I  SPN  0.00  22.50  0.00  0.00  0.00  22.50
W  1013  23.64  105.00  0.00  11.76  0.00  140.40
Totals  23.64  127.50  0.00  11.76  0.00  162.90
*****

```