

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13442B

Date In:	30 JUN 26	Author:	MGRAY
Promised Date:	31 DEC 26	Stock No:	11578
:	:	Year:	2026
Customer Name:	17965 - SONNENBERG, CA	Manufacturer:	FOREST RIVER
Address:	N7160 1ST AVENUE	Brand:	FLAGSTAFF CLASSIC FW
:	WESTFIELD, WI	Model:	371RK
Postal/Zip:	53964	Miles/Hrs:	0
Phone#(res):	6083690482	Exterior Color:	:
Phone#(bus):	:	Unit Type:	FW-FIFTH WHEEL
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	DB: 6/30
Purchased Date:	24 JAN 26	:	:
Delivery Date:	25 APR 26	:	:
InService Date:	:	:	:
Serial#:	4X4FFLN29T1910906	:	:

Job #	Description	JOB INFORMATION	Type	Bill To
4	COMPLAINT:	CUSTOMER STATES LEAK ON ODS FRONT COMPARTMENT	W	1021 FORES
	CAUSE:	The ods compartment door leaks at the rear upper corner. The compartment door is out of the alignment or bent as seen in the pictures. The seal is not making contact with the door letting and water.		
	CORRECTION:	Will need a new compartment door		
	REQUEST:	1.5		
5	COMPLAINT:	FRONT STORAGE COMPARTMENT WHERE BATTERIES ARE IS POSSIBLY DELAMINATING	W	1021 FORES
	CAUSE:	Front compartment door is delaminating the glue must have let loose		
	CORRECTION:	Will need new compartment door		
	REQUEST:	1.5		
6	COMPLAINT:	CUSTOMER STATES DOOR LATCH SCREWS FOR CATCH CAME OUT AND LATCH IS LOOSE IN DOOR	W	1021 FORES
	CAUSE:	Door latch screws came off		
	CORRECTION:	Will need new door latch and screws		
	REQUEST:	.4		
7	COMPLAINT:	CUSTOMER STATES DRIVERS SIDE JACK PIN IS W DIFFICULT TO OPERATE IN AND OUT	1021	FORES
	CAUSE:	Jack Penn was hard to get out was put in at an angle had to readjust the bracket		
	CORRECTION:	Readjusted the bracket seems to be working OK now		
	REQUEST:	.4		

Continued on page 2

Work Order : 13442B

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
8       COMPLAINT:  CUSTOMER STATES SCREW IS MISSING ON          W    1021    FORES
          WINDOW HANDLE BY DINETTE
          CAUSE:      Missing screw
          CORRECTION: Found a screw and replaced it  REQUEST:
                      .5
9       COMPLAINT:  CUSTOMER STATES WOOD TRIM ABOVE DINETTE    W    1021    FORES
          BUBBLING AND FINISH SEEMS TO BE COMING
          OFF
          CAUSE:      Looks like the trim is starting to fall
                      off
          CORRECTION: Will need a new piece of trim    .5
10      COMPLAINT:  CUSTOMER STATES BATHROOM DOOR IS BOWED      W    1021    FORES
          AND CATCHING IN SPOTS
          CAUSE:      Bathroom door is rubbing against the
                      wall
          CORRECTION: Might just need to be adjusted
                      REQUEST: .15
11      COMPLAINT:  CUSTOMER STATES TRIM BEHIND THEATER          W    1021    FORES
          CHAIRS ANOTHER ABOVE SLIDE OUT WITH
          SMALLER COUCH SEAM TAPE IS NOT DOWN
          CORRECTLY PANEL MAY NEED TO BE SECURED
          CAUSE:      The seem tape has bubbles behind it.
                      One of the panels behind the couch has
                      popped loose so we need new seem tape.
          CORRECTION: I have to remove the seem tape  and
                      reattach the panel behind the couch and
                      put new tape on it  REQUEST: .15
12      COMPLAINT:  CUSTOMER STATES SLIDE TOPPER ON DINETTE    W    1021    FORES
          SLIDE IS LOOSE AND SAGGY LAYING ON ROOF
          WITH LIGHT RAIN
          CAUSE:      Slide toppers is sagging checked the
                      springs in the slide topper and the
                      springs are tight I think do to the size
                      of the slide room and how long the
                      topper is it will SAG  do to how big it
                      is
          CORRECTION: Could adjust the slide topper so it
                      tracks straight will not help will the
                      sag  REQUEST: .5

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
4 WARR  MANUFACTURER WARRANTY  JL  W-1021  0.21  140.00  29.40
4 WARR  MANUFACTURER WARRANTY  JL  W-1021  0.29  140.00  40.60
5 WARR  .  JL  W-1021  0.50  140.00  70.00
5 RV31B-4  COMPARTMENT DOOR R&R (  W-1021  0.00  140.00  0.00
6 WARR  MANUFACTURER WARRANTY  JL  W-1021  0.50  140.00  70.00
7 WARR  MANUFACTURER WARRANTY  JL  W-1021  0.50  140.00  70.00

```

Continued on page 3

Work Order : 13442B

```

*****
Job#  Lab Code  Description    LABOUR    Mech Bill to      Hrs      Rate      Total
*****
   8  WARR      MANUFACTURER WARRANTY  JL    W-1021      0.50    140.00     70.00
   9  WARR      MANUFACTURER WARRANTY  JL    W-1021      0.50    140.00     70.00
  10  WARR      MANUFACTURER WARRANTY  JL    W-1021      0.50    140.00     70.00
  11  WARR      MANUFACTURER WARRANTY  JL    W-1021      0.50    140.00     70.00
  12  WARR      MANUFACTURER WARRANTY  JL    W-1021      0.03    140.00      4.20
  12  WARR      MANUFACTURER WARRANTY  JL    W-1021      0.47    140.00     65.80
*****

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras      Tax      Total
*****
W      1021          0.00    630.00      0.00      0.00      0.00     630.00

      Totals          0.00    630.00      0.00      0.00      0.00     630.00
*****

```

&k2S
&k0S