

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	965688
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
		VIN	5ZT2FEXB5NW023319
EVANSVILLE, IN 47725		CHASSIS VIN	
USA		MILEAGE	0
		SITE/WAREHOUSE	320 / 320
Labor rate:	\$150.00	ITEM #	FET320BHDSLE-320
OWNER INFORMATION		DEALER RO #	66731
		CLAIM START DATE	03/17/2022
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description			
	50-134-27-00-001459	Test with Removal of LP Component - LP Gas/LP Gas System/Leak/No Tread Code			
	Complaint, Cause, Correction				
	Original Note : bhoffman@americanrvcenter.com, 2022-03-17 08:32:17 :: OUTSIDE GRILLE WILL NOT CONNECT TO LP LINE OUTSIDE GRILLE WILL NOT CONNECT TO LP LINE. Outside grille has a Flared fitting in LP valve. It Does not have a fitting to connect to Quick connect LP hose. Removed flared fitting and installed a quick connect fitting.				
	Model #	Dlr Sub Hrs	0.50	Sub Labor Amt	\$75.00
	Serial #	Appr Hrs	0.30	Appr Labor Amt	\$45.00
	Notes				
	install quick connect 50-134-01-00-001460 = 0.30				

Submitted	Labor Amt	\$75.00	Approved	Labor Amt	\$45.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$75.00		Total	\$45.00

DEALER _____ DATE _____
SIGNATURE
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE
All repairs described have been inspected and are satisfactory.