

BASDEN RV CENTER, INC D.B.A. AMERICAN RV  
600 E. Baseline Rd.  
Evansville, IN  
47725  
812-867-5200

WARRANTY CLAIM # 66735  
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO  
Customer: 1000 - BASDEN'S AMERICAN RV  
Address: 600 E. BASELINE RD. EVANSVILLE, IN  
USA  
47725

Phone:

Stock Number: 11162 - 2022 MONTANA 3761FL 4YDFM0T24N4701973  
VIN: 4YDFM0T24N4701973 HIN: SER#: 4YDFM0T24N4701973  
Mileage: 0 Work Order Comp: 11 MAY 22  
Auth. No: Dealer #: 1194  
Warr. Date: Work Order Date: 14 MAR 22 Inv #: 376704

\*\*\*\*\*  
WO # Job # Description JOB INFORMATION  
\*\*\*\*\*  
66735 1 NO POWER TO FRIDGE OR CHAIRS GFI HAS NOT POWER.  
I CHECKED OUT THE NEW INVERTER AND HAD NO OUTPUT SO I CHECKED  
THE INPUT WIRES AND CHECKED THE POLARITY AND CHECKED THE 12  
VOLT INPUT ALL WAS OK I FOUND THAT THERE IS IN INPUT FOR  
IGNITION SO I TRIED IT AND IT DIDNT HELP. SO I ASKED DONNIE IF  
THEY SENT A NEW CONTROL AND HE BROUGHT IT TO ME I INSTALLED IT  
AND EVERYTHING STARTED WORKING . I THEN REINSTALLED THE OUTLET S  
ON THE INSIDE AND CHECKED OPERATION..  
no power to ref or gfi outlet chased wires and they go under  
cabinet and cant see where they go,took ref out to check wires  
behind it and took out basement panels to get to wires and follow  
them.found inverter is bad on one side.TOOK CAMPER OUT.PARTS CAME  
IN WENT AND GOT CAMPER AND BROUGHT IN TOOK OUT OLD INVERTER AND  
INSTALLED NEW INVERTER CHECKED FOR POWER INSIDE AND STILL NO  
POWER INSIDE CHECKED INVERTER AND SAME THING NO POWER COMING OUT  
OTHER SIDE TO FEED INSIDE CAMPER,TOOK INVERTER BACK OUT AND PUT  
OLD ONE BACK IN PUT INVERTER, CLOSED CAMPER BACK UP AND SET BACK  
ON LOT FOR SECOND TIME. BROUGHT CAMPER BACK IN AGAIN TO WORK ON  
INVERTER.INSTALLED NEW INVERTER STILL NOTHING CHASING WIRES TO  
FIND PROBLEM, I CHECKED OUT THE NEW INVERTER AND HAD NO OUTPUT  
SO I CHECKED THE INPUT WIRES AND CHECKED THE POLARITY AND  
CHECKED THE 12 VOLT INPUT ALL WAS OK I FOUND THAT THERE IS IN  
INPUT FOR IGNITION SO I TRIED IT AND IT DIDNT HELP. SO I ASKED  
DONNIE IF THEY SENT A NEW CONTROL AND HE BROUGHT IT TO ME I  
INSTALLED IT AND EVERYTHING STARTED WORKING . I THEN REINSTALLED  
THE OUTLET S ON THE INSIDE AND CHECKED OPERATION..

Claim : 66735

\*\*\*\*\*  
 WO #      Job #      Description      JOB INFORMATION  
 \*\*\*\*\*

66735      2      DOOR TO HALF/BATH IN KITCHEN COMING APART  
 UNBOXED DOOR IN A FOAM MESS TO GET OU ,TOOK OUT DOOR IN CAMPER  
 AND TRANSFERRED HINGES AND DOOR KNOB SET IN PLACE AND MOVED TRIM  
 FOR DOOR TO FIT,THAT IS WHAT TORE THE OTHER DOOR UP.

\*\*\*\*\*

Part No	Job#	Description	PARTS	Qty	Price	Total
686127	1	Inverter - 2000 Watt HF - Sensata		1.00	697.02	697.02
638934	2	Passage - Door - 1		1.00	184.61	184.61

\*\*\*\*\*

\*\*\*\*\*

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	1	MISCELLANEOUS REPAIR		0.00	150.00	0.00
Z990	1	MISCELLANEOUS REPAIR		0.25	150.00	37.50
Z990	1	MISCELLANEOUS REPAIR		0.00	150.00	0.00
Z990	1	MISCELLANEOUS REPAIR		0.00	150.00	0.00
Z990	1	MISCELLANEOUS REPAIR		0.25	150.00	37.50
Z990	1	MISCELLANEOUS REPAIR		0.00	150.00	0.00
Z990	1	MISCELLANEOUS REPAIR		0.00	150.00	0.00
Z990	1	MISCELLANEOUS REPAIR		0.00	150.00	0.00
Z990	1	MISCELLANEOUS REPAIR		0.00	150.00	0.00
Z990	1	MISCELLANEOUS REPAIR		0.00	150.00	0.00
Z990	1	MISCELLANEOUS REPAIR		0.00	150.00	0.00
Z990	1	MISCELLANEOUS REPAIR		0.00	150.00	0.00
Z990	2	MISCELLANEOUS REPAIR		0.50	150.00	75.00

\*\*\*\*\*

\*\*\*\*\*

Excode	Job#	Description	EXTRAS	Qty	Price	Total
FRT	1	UPS-INVERTER		1.00	32.45	32.45
FRT	2	FREIGHT & CRATE - PASSAGE DOOR		1.00	137.16	137.16

\*\*\*\*\*

Parts Total:      881.63  
 Labour Total:     150.00  
 Sublet Total:     0.00  
 Extras Total:     169.61

>>>> Claim Total:    1,201.24

Customer Signature: \_\_\_\_\_

Date: \_\_\_\_\_