



1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$817.50

RO# : 40877 Tag# : SJ970941

Check-in: Thu Jun 4, 2026 | 9:38 AM
Ready for Pickup: Tue Jun 23, 2026 | 11:59 AM
Promise Time: Tue Jun 9, 2026 | 6:00 PM

Customer
James Anderson
1246688
+1 - (715) 790 - 1802
jimanderson1102@gmail.com
2383 20 1/2 Street
Rice Lake, WI 54868

Pickup-Customer
Same as Customer

Billing-Customer
Same as Customer

Vehicle
2025 KEYSTONE
KODIAK
4YDTKDN26SJ970941
1 Mi In
Sold Date: 06/15/2026
Stock #: KS25-08

Service Advisor
BONNIE SEEMANN
bonnie

A.	WT	WALK THRU	Internal Pay	\$250.00
----	----	-----------	--------------	----------

Job added by BONNIE SEEMANN on Thu Jun 4, 2026 | 9:38 AM

1. Walk through

Op.1 WT -WALK THRU

Labor Sale: \$250.00

Labor Cost: \$45.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
turnerl	-	0	0	0	\$0.00	\$0.00
921	-	2.02	2.5	2.5	\$250.00	\$45.00

1. Gave walk through and installed old weight hitch

Total Labor Sale	Total Labor Cost	Total Parts Sale	Total Parts Cost
\$250.00	\$45.00	\$0.00	\$0.00

B.	TT	INSTALL BATTERY BATTERY BOX STARTER KIT AND COUPLER PIN	Internal Pay	\$206.00
----	----	---	--------------	----------

Job added by BONNIE SEEMANN on Thu Jun 4, 2026 | 9:38 AM

Op.1 TT -INSTALL BATTERY BATTERY BOX STARTER KIT AND COUPLER PIN

Labor Sale: \$30.00

Labor Cost: \$10.80

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
turnerl	-	0.23	0.3	0.3	\$30.00	\$10.80
921	-	0	0	0	\$0.00	\$0.00





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$817.50

RO# : 40877 Tag# : SJ970941

Check-in: Thu Jun 4, 2026 | 9:38 AM
Ready for Pickup: Tue Jun 23, 2026 | 11:59 AM
Promise Time: Tue Jun 9, 2026 | 6:00 PM

Customer James Anderson 1246688 +1 - (715) 790 - 1802	Billing-Customer Same as Customer	Vehicle 2025 KEYSTONE KODIAK 4YDTKDN26SJ970941	Service Advisor BONNIE SEEMANN bonnie
---	---	--	--

Op.1 TT -INSTALL BATTERY BATTERY BOX STARTER KIT AND COUPLER PIN

Labor Sale: \$30.00

Labor Cost: \$10.80

1. INSTALLED BATTERY BOX BATTERY AND STARTER KIT

Parts

Parts Total Sale Amount \$176.00

Parts Total Cost Amount \$129.24

Name	Quantity	Unit Price	Sale Price	Cost Price
24DCM - DEEP CYCLE 24	1	\$110.00	\$110.00	\$90.72
03041500 - BATT BOX GROUP 24	1	\$16.00	\$16.00	\$7.90
CMC47807 - STARTER KIT BOX - STANDARD	1	\$45.00	\$45.00	\$29.06
JRP01091 - SMALL COUPLER LOCK PIN	1	\$5.00	\$5.00	\$1.56

Total Labor Sale
\$30.00

Total Labor Cost
\$10.80

Total Parts Sale
\$176.00

Total Parts Cost
\$129.24

C. DW	DEWINTERIZATION OF FRESH WATER SYSTEM	Internal Pay	\$82.50
-------	---------------------------------------	--------------	---------

Job added by BONNIE SEEMANN on Thu Jun 4, 2026 | 9:38 AM

1. dewinterize

Op.1 DW -DEWINTERIZATION OF FRESH WATER SYSTEM

Labor Sale: \$82.50

Labor Cost: \$18.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
turnerl	-	0.28	0.5	0.5	\$82.50	\$18.00
921	-	0	0	0	\$0.00	\$0.00

1. dewinterize





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$817.50

RO# : 40877 Tag# : SJ970941

Check-in: Thu Jun 4, 2026 | 9:38 AM
Ready for Pickup: Tue Jun 23, 2026 | 11:59 AM
Promise Time: Tue Jun 9, 2026 | 6:00 PM

Customer James Anderson 1246688 +1 - (715) 790 - 1802	Billing-Customer Same as Customer	Vehicle 2025 KEYSTONE KODIAK 4YDTKDN26SJ970941	Service Advisor BONNIE SEEMANN bonnie
---	---	--	--

Total Labor Sale \$82.50	Total Labor Cost \$18.00	Total Parts Sale \$0.00	Total Parts Cost \$0.00
-----------------------------	-----------------------------	----------------------------	----------------------------

D. MISCELLANEOUS	DEALER STATES GLUE ON FLOOR BY BATHROOM DOOR.	Warranty Pay	\$82.50
------------------	---	--------------	---------

Job added by BONNIE SEEMANN on Thu Jun 4, 2026 | 9:38 AM

1. Glue on floor by bathroom door.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$82.50

Labor Cost: \$18.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
turnerl	-	0.42	0.5	0.5	\$82.50	\$18.00
921	-	0	0	0	\$0.00	\$0.00

1. Removed glue by bathroom door. Was some kind of hard epoxy, had to chip it away carefully without damaging Lino. REQUESTING .40 HRS

Total Labor Sale \$82.50	Total Labor Cost \$18.00	Total Parts Sale \$0.00	Total Parts Cost \$0.00
-----------------------------	-----------------------------	----------------------------	----------------------------

E. MISCELLANEOUS	DEALER TRIM ON SLIDE BY COUCH, WHITE PLASTIC PIECE STICKING OUT.	Warranty Pay	\$115.50
------------------	--	--------------	----------

Job added by BONNIE SEEMANN on Thu Jun 4, 2026 | 9:38 AM

1. Plastic trim by sofa sticking out.





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$817.50

RO# : 40877 Tag# : SJ970941

Check-in: Thu Jun 4, 2026 | 9:38 AM
Ready for Pickup: Tue Jun 23, 2026 | 11:59 AM
Promise Time: Tue Jun 9, 2026 | 6:00 PM

Customer James Anderson 1246688 +1 - (715) 790 - 1802	Billing-Customer Same as Customer	Vehicle 2025 KEYSTONE KODIAK 4YDTKDN26SJ970941	Service Advisor BONNIE SEEMANN bonnie
---	---	--	--

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: **\$115.50**

Labor Cost: **\$25.20**

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
turnerl	-	0.63	0	0.7	\$0.00	\$25.20
921	-	0	0	0	\$0.00	\$0.00

1. Removed facia, found trim was a tad too long, and staples had pulled out of middle. Removed all staples, trimmed bottom, and re-installed. Re-installed facia. REQUESTING .40 HR

Total Labor Sale
\$115.50

Total Labor Cost
\$25.20

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

F. MISCELLANEOUS	DEALER STATES WHEN SLIDEOUT IS OUT, CUSTOMER IS WONDERING IF PLASTIC TUBING CAN BE PUT OVER THE WIRES.	Internal Pay	\$48.00
-------------------------	---	---------------------	----------------

Job added by BONNIE SEEMANN on Thu Jun 4, 2026 | 9:38 AM

1. Customer was wire Luke on wires on slide out.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: **\$48.00**

Labor Cost: **\$14.40**

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
turnerl	-	0.38	0.4	0.4	\$48.00	\$14.40
921	-	0	0	0	\$0.00	\$0.00

1. Hoping they were talking about wires outside under slide. They go to running light on slide wrap metal. Cut off big connectors, installed heat shrink butt connectors, so they were in line. Added a section of wire Luke over wires, and taped the section where Luke's over lap with other set of wires. When running room in noticed wires inside, Above slide out. Covered with wire loom after noticing them.

Total Labor Sale
\$48.00

Total Labor Cost
\$14.40

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$817.50

RO# : 40877 Tag# : SJ970941

Check-in: Thu Jun 4, 2026 | 9:38 AM
Ready for Pickup: Tue Jun 23, 2026 | 11:59 AM
Promise Time: Tue Jun 9, 2026 | 6:00 PM

Customer James Anderson 1246688 +1 - (715) 790 - 1802	Billing-Customer Same as Customer	Vehicle 2025 KEYSTONE KODIAK 4YDTKDN26SJ970941	Service Advisor BONNIE SEEMANN bonnie
---	---	--	--

G. MISCELLANEOUS	DEALER STATES THE LOCK SPINS FOR THE BAGGAGE DOOR FOR OUTSIDE FRIDGE.	Warranty Pay	\$33.00
-------------------------	--	---------------------	----------------

Job added by BONNIE SEEMANN on Thu Jun 4, 2026 | 9:38 AM

1. Lock on baggage door spins.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$33.00

Labor Cost: \$7.20

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
turnerl	-	0.18	0.2	0.2	\$33.00	\$7.20
921	-	0	0	0	\$0.00	\$0.00

1. Checked baggage door, found nut on inside of cam lock was not tight. Removed latch tab, tightened nut on cam lock, and installed latch tab. Works as hould now. REQUESTING .25 HRS

Total Labor Sale
\$33.00

Total Labor Cost
\$7.20

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$817.50

RO# : 40877 Tag# : SJ970941

Check-in: Thu Jun 4, 2026 | 9:38 AM
Ready for Pickup: Tue Jun 23, 2026 | 11:59 AM
Promise Time: Tue Jun 9, 2026 | 6:00 PM

Customer
James Anderson
1246688
+1 - (715) 790 - 1802

Billing-Customer
Same as Customer

Vehicle
2025 KEYSTONE
KODIAK
4YDTKDN26SJ970941

Service Advisor
BONNIE SEEMANN
bonnie

	Category	Sale	Cost
	Labor	\$641.50	\$138.60
	Parts	\$176.00	\$129.24
	Sublet	\$0.00	\$0.00
	Sublet Labor	\$0.00	\$0.00
	Sublet Parts	\$0.00	\$0.00
	Fees	\$0.00	\$0.00
	Discounts	\$0.00	-
	Tax	\$0.00	-
	Deductible	\$0.00	-
	Insurance/Warranty	\$0.00	-
	Invoice Total	\$817.50	\$267.84

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
B	TT	Fri Jun 12, 2026	8:07 AM	8:20 AM	0.23 hrs	I	turnerl	0.3 hrs
Tag: Regular Hour			Reason: -					
C	DW	Fri Jun 12, 2026	8:21 AM	8:38 AM	0.28 hrs	I	turnerl	0.5 hrs
Tag: Regular Hour			Reason: -					
D	MISC	Fri Jun 12, 2026	8:38 AM	9:03 AM	0.42 hrs	W	turnerl	0.5 hrs
Tag: Regular Hour			Reason: -					
E	MISC	Fri Jun 12, 2026	9:51 AM	10:29 AM	0.63 hrs	W	turnerl	0.7 hrs
Tag: Regular Hour			Reason: -					
F	MISC	Fri Jun 12, 2026	10:29 AM	10:52 AM	0.38 hrs	I	turnerl	0.4 hrs
Tag: Regular Hour			Reason: -					





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$817.50

RO# : 40877 Tag# : SJ970941

Check-in: Thu Jun 4, 2026 | 9:38 AM
Ready for Pickup: Tue Jun 23, 2026 | 11:59 AM
Promise Time: Tue Jun 9, 2026 | 6:00 PM

Customer
James Anderson
1246688
+1 - (715) 790 - 1802

Billing-Customer
Same as Customer

Vehicle
2025 KEYSTONE
KODIAK
4YDTKDN26SJ970941

Service Advisor
BONNIE SEEMANN
bonnie

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
G	MISC	Fri Jun 12, 2026	11:11 AM	11:22 AM	0.18 hrs	W	turnerl	0.2 hrs
Tag: Regular Hour			Reason: -					
A	WT	Mon Jun 15, 2026	1:19 PM	3:20 PM	2.02 hrs	I	921	2.5 hrs
Tag: Regular Hour			Reason: -					
A	WT	-	-	-	0 hrs	I	turnerl	0 hrs
B	TT	-	-	-	0 hrs	I	921	0 hrs
C	DW	-	-	-	0 hrs	I	921	0 hrs
D	MISC	-	-	-	0 hrs	W	921	0 hrs
E	MISC	-	-	-	0 hrs	W	921	0 hrs
F	MISC	-	-	-	0 hrs	I	921	0 hrs
G	MISC	-	-	-	0 hrs	W	921	0 hrs

Accounting Info - Warranty

GL Account #	Control #	Franchise	Amount
11400	40877	LINK RV	\$231.00
57200	40877	LINK RV	-\$231.00
67200	40877	LINK RV	\$50.40
14400	turnerl	LINK RV	-\$50.40
14400	921	LINK RV	\$0.00





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$817.50

RO# : 40877 Tag# : SJ970941

Check-in: Thu Jun 4, 2026 | 9:38 AM
Ready for Pickup: Tue Jun 23, 2026 | 11:59 AM
Promise Time: Tue Jun 9, 2026 | 6:00 PM

Customer
James Anderson
1246688
+1 - (715) 790 - 1802

Billing-Customer
Same as Customer

Vehicle
2025 KEYSTONE
KODIAK
4YDTKDN26SJ970941

Service Advisor
BONNIE SEEMANN
bonnie

Accounting Info - Internal

GL Account #	Control #	Franchise	Amount
14300	KS25-08	LINK RV	\$586.50
57300	40877	LINK RV	-\$410.50
67300	40877	LINK RV	\$88.20
14400	turnerl	LINK RV	-\$43.20
14400	921	LINK RV	-\$45.00
54000	40877	LINK RV	-\$176.00
64000	40877	LINK RV	\$129.24
14000	40877	LINK RV	-\$129.24

