



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73648
Promised Date:
06/11/26



WO #: 73648 (Appointment Date: 30 JUN 2026 - Time: 10:15am)

Customer Name: 19667 - STEIDER,
TIMOTHY D

Completed Date:

Invoice#:

Author: ADVISOR

Stock Desc: 9558 2026 BAY STAR 3225

Serial#: 142199

Chassis#: 1F66F5DN3S0A01256

Miles/Hrs:

Tag#: 7341

Purchased Date: 27 DEC 25

Warranty Date: 27 DEC 25

Date In: 30 JUN 26

Time In:

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES BOTH BLACK OUT SHADES AT DRIVERS AREA WILL ROLL DOWN FINE BUT WILL NOT ROLL UP

CAUSE: Attempted to load spring tension. Shades will not retract.

CORRECTION: Replace both shade assemblies
Requesting. .5 hr

Labor

Job #	Description	Total
1	DAY/NIGHT SHADE (2)	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: CUSTOMER STATES AWNING WILL NOT GO OUT ALL THE WAY AND BEEPS **STATES THERE IS A LOOSE WIRE TOWARDS THE FRONT OF THE COACH**

CAUSE: Low batteries in awning box causing warning beep. Adhesion failure on awning light wiring.

CORRECTION: Replaced both aaa batteries at awning box. Removed old adhesive. Re routed and resecured awning light wiring with new adhesive tape. Tested awning for full open/close. Audible beep is now gone. Awning operation is normal. Completed
Requesting. .75 hr

Labor

Job #	Description	Total
2	AWNING DIAGNOSE	N/C

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: JOB ADDED: CUSTOMER STATES SCREEN BY DINETTE TABLE WILL NOT GO UP ALL THE WAY

CAUSE: Out of adjustment

Customer #: 19667
STEIDER, TIMOTHY D



CORRECTION: Performed retract point adjustment and tested. Completed
Requesting .2 hr

Labor		
Job #	Description	Total
3	WINDOW SCREEN	N/C
Subtotal for Job #3:		0.00

Job #4 - Warranty

COMPLAINT: JOB ADDED: CUSTOMER STATES BLACK OUT SHADE/SCREEN OVER KITCHEN SINK IS REVERSED, COMPARED TO THE REST OF THE SHADES

CAUSE: Installed backwards

CORRECTION: Removed and reinstalled 180 degrees. Completed
Requesting .3 hr

Labor		
Job #	Description	Total
4	DAY/NIGHT SHADE	N/C
Subtotal for Job #4:		0.00

Job #5 - External

COMPLAINT: JOB ADDED: CUSTOMER STATES ENTRY SCREEN DOOR LOCK BROKE

CAUSE: Broken missing piece

CORRECTION: Installed missing broken piece. Tested
Requesting .2 hr

Labor		
Job #	Description	Total
5	SCREEN DOOR LATCH R&R	0.00

Other Services				
Code	Description	Qty	Price	Total
SS-I	SHOP SUPPLIES - INTERNAL	1.00	0.00	0.00
Subtotal for Job #5:				0.00

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	0.00

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

W/O: 73648
Promised Date: 06 JUL 26



Customer #: 19667
STEIDER, TIMOTHY D



Customer Signature : _____

Date: 01 Jul 2026

W/O: 73648
Promised Date: 06 JUL 26



Customer #: 19667
STEIDER, TIMOTHY D



Customer Work
Order

