



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73608
Promised Date:
48 1111 26



WO #: 73608 (Appointment Date: 23 JUN 2026 - Time: 10:15am)

Customer Name: 61388 - PEYTON,
RHONDA

Completed Date:

Invoice#:

Author: BRIAN

Stock Desc: 9476 2025 OPEN RANGE

3X 287RLS

Serial#: 58TCM0BS2S3B53091

Date In: 23 JUN 26

Chassis#: 58TCM0BS2S3B53091

Time In:

Miles/Hrs:

Tag#: 7330

Purchased Date: 28 MAR 26

Warranty Date: 28 MAR 26

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES TRAYS IN REFER WILL NOT FIT PROPERLY

CAUSE: Trays do not latch or hook into the lower part of the refrigerator door

CORRECTION: Recommend ordering replacement narrow door trays that latch or lock in place as
designed for this refrigerator

.35HRS

Labor

Job #	Description	Total
1	REFER TRAYS	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: CUSTOMER STATES JWRAP SCREWS LOOSE

CAUSE: Stripped and missing screws

CORRECTION: Removed the stripped screws

Replaced them with a larger diameter screw

Total of 4 screws

Work completed

.25HRS

Labor

Job #	Description	Total
2	J WRAP	N/C

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: CUSTOMER STATES SCREWS LOOSE AT TRAYS FOR RECLINERS

CAUSE: Screw fell out other screws stripped

Customer #: 61388
PEYTON, RHONDA





CORRECTION: Remove all the screws all the way around the entire folder lifted the holder up rotated it slightly reset all the screws and new screw holes. Replace the one missing screw. The job is now complete.
 .25HRS

Labor		
Job #	Description	Total
3	RECLINER TRAYS	N/C
Subtotal for Job #3:		0.00

Job #4 - Warranty

COMPLAINT: CUSTOMER STATES SCREWS LOOSE AT SOFA AND SCREWS TO FLOOR LOOSE

CAUSE: Couch loose missing screws

CORRECTION: Open the couch to find out why the couch is loose from the floor. Found there was only one screw on the angle brackets holding the couch in place in the screw was severely bent. Reset the couch in place make sure that the back opened open normally and folded into place normally reset the screws in the floor and new holes with larger more heavy duty screws total of four screws. Check the couch again for operation, but it opened and closed couches operating correctly opening and closing. Job is now complete.
 .25HRS

Labor		
Job #	Description	Total
4	SOFA	N/C
Subtotal for Job #4:		0.00

Job #5 - Warranty

COMPLAINT: CUSTOMER STATES REAR JACKS FAILED (BENT)

CAUSE: CUSTOMER LOOSENED STRONG ARM BEFORE RAISING / STRONG ARM BOUND UP CAUSING FAILER

CORRECTION: Passenger side rear electric jack bent
 Mounting plate behind the jack and motor bent
 Mounting plate on the frame (welded) also bent
 Found bolt missing at the top behind the motor missing both sides of unit
 Recommend full replacement of the electric jack on the passenger side
 Straighten the welded mounting plate
 Adding a third bolt to the drivers side rear jack
 Installing new jack
 2.5HRS

Labor		
Job #	Description	Total
5	REAR JACKS	N/C
Subtotal for Job #5:		0.00

Job #6 - Warranty

COMPLAINT: CUSTOMER STATES LARGE DRAWER UNDER BED CAME OPEN IN TRANSIT (DAMAGED)

CAUSE: Drawer rail support broke off

CORRECTION: Found the under bed drawer, the drawer rail support broke, causing the drawer to come out not allowing the door guides operate correctly, tearing the bed and facia. The drawer bottom fell out. Recommend complete removal of the footboard bed, facia, and full replacement.
 Rebuilding the drawer rail supports
 Replacement of the entire drawer
 Replacement of the drawer guides
 The actual drawer size is 37 x 14
 The drawer face is 47 3/8 x 9 and three-quarter
 The footboard face is 57 x 14 5/8



To rebuild the drawer guide supports will require adding some side to side support to prevent the drawer from flexing from side to side. There are no supports to prevent the drawer from moving side to side. It will involve cutting some one by fours and attaching it to the side of the bed.

3.5HRS

Labor

Job #	Description	Total
6	DRAWER	N/C

Subtotal for Job #6: 0.00

Parts Total: 0.00

Labour Total: 0.00

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 0.00

NOTICE:

DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

****MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND****

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 24 Jun 2026

W/O: 73608
Promised Date: 10 JUL 26



Customer #: 61388
PEYTON, RHONDA

