



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73598
Promised Date:
26 JUN 26



WO #: 73598 (Appointment Date: 22 JUN 2026 - Time: 03:45pm)

Customer Name: 61799 - BELTRAN,
MONICA

Completed Date:

Invoice#:

Author: BRIAN

Stock Desc: 9557 2026 AVENGER 22MK

Serial#: 5ZT2AVLB4TB940664

Chassis#: 5ZT2AVLB4TB940664

Miles/Hrs:

Tag#: 7257

Purchased Date: 19 JUN 26

Warranty Date: 19 JUN 26

Date In: 22 JUN 26

Time In:

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES THE METAL (SIDEWALL) SEPARATED FROM WHEEL WELL
MOLDING AT DRIVER'S SIDE

CAUSE: STAPLES PULLED LOOSE ALLOWING METAL TO MOVE

CORRECTION: REMOVE AND REPLACE BOTTOM TWO METAL PANELS.
4.50HRS

Labor

Job #	Description	Total
1	WHEEL WELL	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: CUSTOMER STATES ENTRY DOOR VERY HARD TO OPERATE (BINDS)

CAUSE: Most likely caused by road vibrations

CORRECTION: The door was binding when you shut it. Applied pressure to screen door and reg door to get it back into position for proper operation. open and shut both door repeatedly to check for proper operation. It was working smooth for me . Screen is completely out of the way with ample clearance.. I tightened all the fasteners holding the door to the frame. With the door almost closed I applied fast pressure to push the hinges back to the original location. The door latch is now the only thing that touches the strike plate when closing operation is induced. Then I got a rag and whipped and cleaned all my fingerprints and scuffs.

.30HRS

Labor

Job #	Description	Total
2	ENTRY DOOR	N/C

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: CUSTOMER STATES RESEAL MOLDING AT WHEEL WELL AT PASSENGER SIDE

Customer #: 61799
BELTRAN, MONICA



CAUSE: CAULKING SEPARATING

CORRECTION: SCRAPED AND RESEALED WHEEL WELL MOLDING
.20HRS

Labor		
Job #	Description	Total
3	WHEEL WELL	N/C
Subtotal for Job #3:		0.00

Job #4 - Warranty

COMPLAINT: CUSTOMER STATES INTERIOR CABINET PANEL UNEVEN

CAUSE: Manufacturer defect

CORRECTION: I removed the panels hiding the control panel . And a board that braces it. Softly I pry the bottom board up to see what was making it bow.. the board was just installed a little high. Lower the screws and the board a inch. Then I checked for proepr placement and put back together the rest of the cabnit. Then I removed some of trim pieces and repositioned them to make the cabnit look more complete . Then I got a clean rag and cleaned up any marks created by me.. them I took time to write all this up.
1.00HRS

Labor		
Job #	Description	Total
4	INTERIOR CABIENT	N/C
Subtotal for Job #4:		0.00

Job #5 - Warranty

ARTERO: 505-261-0462

Subtotal for Job #5: 0.00

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	0.00

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 26 Jun 2026

W/O: 73598
Promised Date: 26 JUN 26



Customer #: 61799
BELTRAN, MONICA

