

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106
BASDEN RV CENTER INC
DBA AMERICAN RV CENTER
600 E BASELINE ROAD

EVANSVILLE, IN 47725
USA

Labor rate: \$150.00
OWNER INFORMATION

CLAIM STATUS Authorized
CLAIM 973128
CLAIM ORIGIN WEB
ORIGINAL CLAIM ID
VIN 5ZT2CARB9NU039758
CHASSIS VIN
MILEAGE 0
SITE/WAREHOUSE 103 / 103
ITEM # CAT263BHCKLE
DEALER RO # 66796
CLAIM START DATE 03/23/2022
CLAIM END DATE 01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1 Operation Code Operational Description
70-178-01-00-002144 Suburban Bi-Fold Stove Top Cover - Appliances/Range (Suburban)/
Replace/No Tread Code

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2022-03-23 14:02:58 :: THE EDGES OF THE STOVE TOP ARE NOT LINED UP PROPERLY. CUSTOMER UNSURE IS THIS CAN BE ADJUSTED OR IF THE STOVE WILL NEED TO BE REPLACED. STOVE WAS OFF CENTER PULLED STOVE TOP FOWARD AND SECURED WITH PROVIDED SCREWS TO MOUNTING TABS .

Model #	NA	Dlr Sub Hrs	0.10	Sub Labor Amt	\$15.00
Serial #	NA	Appr Hrs	0.10	Appr Labor Amt	\$15.00

Notes

Labor

Line# 2 Operation Code Operational Description
30-102-01-00-001096 Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior
Moldings/Replace/No Tread Code

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2022-03-23 14:12:43 :: CUSTOMER STATES THAT THERE IS TRIM ON THE FRONT OF THE OFF DOOR SIDE SLIDE THAT HAS A GAP AND IS ALLOWING PLYWOOD TO SHOW THROUGH. TRIM NEEDS ADJUSTED TO HIDE PLYWOOD. REMOVED TRIM AT BOTTOM. MOVED OVER TO HIDE PLYWOOD. SECURED WITH STAPLES AND APPLIED PUTTY TO HOLES.

Model #		Dlr Sub Hrs	0.20	Sub Labor Amt	\$30.00
Serial #		Appr Hrs	0.20	Appr Labor Amt	\$30.00

Notes

Submitted	Labor Amt	\$45.00	Approved	Labor Amt	\$45.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$45.00		Total	\$45.00

DEALER
SIGNATURE

DATE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER
SIGNATURE

DATE

All repairs described have been inspected and are satisfactory.