



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 66799
Promised Date: 30 APR 22

CUSTOMER WORK ORDER

WO #: 66799 (Appointment Date: 17 MAR 2022 - Time: 07:00am)

Customer: 52297 - THACKER, TYLER -
618-553-1828

Tag:

Author: BJW

Location: 0411 HAVE DH DO REPAIRS

Stock #: 10917

Stock Desc: 2022 TT FOREST RIVER

CHEROKEE GREY WOLF 26DBH

Chassis #: 4X4TCKB2XNK079276

Serial #: 4X4TCKB2XNK079276

Mileage: 0

Licence:

Invoice #:

Date In: 17 MAR 22

Promised: 30 APR 22

Date Sched:

Completed: 13 APR 22

Warr. Date: 26 FEB 22

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES THAT WHEN RUNNING THE SLIDE ROOM OUT, ONE MOTOR PERFORMS CORRECTLY, BUT THE MOTOR NEAR THE TV GOES OUT A LITTLE WAYS AND THEN STOPS. CUSTOMER CAN RUN ROOM BACK IN, BUT IT DOES NOT RESET. HE HAS THE SAME PROBLEM WHEN HE RUNS IT OUT THE NEXT TIME.

CORRECTION: CHECKED CORD TO MAKE SURE IT WAS GOOD AND CHECKED MOTOR TO SEE IF IT GOOD, TOOK SCREWS OUT OF OUTSIDE RAIL AND PUSHED ROOM OUT TO SEE BLOCK AND GEAR AND SHOE, FOUND SHOE WAS BROKE AND RAIL HAD METAL SHAVINGS, FILLED OUT PAPER WORK TO ORDER PARTS, WAITING ON APPROVAL AND PARTS. parts came in brought camper back in and ran room out and took off both rails had to cut new rails to size replaced top shoe and roller got to bottom and no block was here to replace waiting on parts again. put slide room in and gathered up parts and put back in walk thru area. PULLED CAMPER OUT OF WALK THRU AREA AND PUT IN MY BAY SLIDE OUT ROOM AND PUT RAIL SYSTEM BACK IN SLIDE AND SEALED, SLIDE WORKS FINE NOW.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	150.00
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	60.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	150.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	150.00

Parts

Part #	Description	Qty	Price	Total
366158	Inverted Dual Rack	1.00	435.92	435.92
238893	SPUR GEAR	1.00	40.45	40.45
379076	BLOCK KIT - SCHWIN	1.00	61.33	61.33
379076	BLOCK KIT - SCHWIN	1.00	52.59	52.59

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT	1.00	29.75	29.75
FRT	UPS-BEARING BLOCK	1.00	10.99	10.99
FRT	UPS-BEARING BLOCK KIT	1.00	8.54	8.54



Customer #: 52297
THACKER, TYLER

Subtotal for Job #1: 1,149.57

Job #SUMMER - Internal

COMPLAINT: DE-WINTERIZE UNIT

NOTE: NO CHARGE TO CUSTOMER. HE PURCHASED IN 02/22

CORRECTION: dewinterized.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #SUMMER: 0.00

Parts Total: 590.29
Labour Total: 510.00
Sublet Total: 0.00
Extras Total: 49.28

WORK ORDER TOTAL: 1,149.57

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 15 Apr 2022

W/O: 66799
Promised Date: 30 APR 22



Customer #: 52297
THACKER, TYLER

