

Claim Response

Claim: C3048245

Non-Warranty Goodwill Adjustment

Last Modified by stutk

Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed warranty rate	Type	Date Of Purchase
C3048245	66813	3/28/2022	3/30/2022	4YDT26023M3101210		1194	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	150.00	0.00	SA21-414	7/11/2020

Deny code	Item number	Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
	446897	Hose - LP - 12" Pigtail	2.00	0.00	6.65	15.00	15.30	0.00	0.00	0.00	Approved
5121839											
	692585	Regulator - Kit - Auto Change	1.00	0.00	48.79	15.00	56.11	0.00	0.00	0.00	Approved

5121839

Component Model: 6020

Component Serial Number: N 20 03

Deny code	Operation	Description	Srvc advisory	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	7141442B	Safety Advisory 21-414 Winn-Tec Complaint: KEYSTONE SAFETY ADVISORY LP REGULATOR RECALL #21-414 SECTION:71 COMPONENT:414 OPERATION:7141442B PART#380444 Cause: replace regulator Correction: removed regulator from tanks, removed main line off camper. removed regulator from main line and installed new regulator, bracket and 2 hoses for tanks. secured main line to unit. ran furnace to check function of regulator. (AP KBS)		0.50	0.50	75.00	0.00	1	0.50	Approved

Submitted parts & subLet 71.41
Submitted labor & subLet 75.00
Submitted freight: 0.00
Tax: 0.00
Total Submitted: 146.41

Approved parts & subLet 71.41
Approved labor & subLet 75.00
Approved freight: 0.00
Tax: 0.00
Total approved: 146.41