

Claim Response

Claim: C3042196

Non-Warranty Goodwill Adjustment

Last Modified by C2275

Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed warranty rate	Type	Date Of Purchase
C3042196	66818	3/23/2022	3/24/2022	4YDT26021M3105465		1194	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	150.00	0.00	SA21-414	1/23/2021

Deny code	Item number	Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
	446897	Hose - LP - 12" Pigtail	2.00	0.00	6.65	15.00	15.30	0.00	0.00	0.00	Parts Under Review
	692585	Regulator - Kit - Auto Change	1.00	0.00	48.79	15.00	56.11	0.00	0.00	0.00	Parts Under Review

Component Model: 6020

Component Serial Number: N2032

Deny code	Operation	Description	Srvc advisory	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	7141442B	Safety Advisory 21-414 Winn-Tec Complaint: KEYSTONE SAFETY ADVISORY LP REGULATOR RECALL #21-414 SECTION:71 COMPONENT:414 OPERATION:7141442B PART#380444 Cause: regulator replacement Correction: removed regulator from tanks, removed main line off camper. removed regulator from main line and installed new regulator, bracket and 2 hoses for tanks. secured main line to unit. ran furnace to check function of regulator.		0.50		0.00	0.00	1	0.50	Pending approval

Submitted parts & subLet 71.41
Submitted labor & subLet 75.00
Submitted freight: 0.00
Tax: 0.00
Total Submitted: 146.41

Approved parts & subLet 0.00
Approved labor & subLet 0.00
Approved freight: 0.00
Tax: 0.00
Total approved: 0.00