



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73521
Promised Date:
44 JUN 26



WO #: 73521

Customer Name: 1000 - MYERS "RV"
CENTER, INC.

Completed Date:

Invoice#:

Author: C.MCCLENIN

Stock Desc: 9608 2026 TRACER 235RK

Serial#: 5ZT2TRNB7TB526454

Chassis#: 5ZT2TRNB7TB526454

Miles/Hrs:

Tag#:

Purchased Date: 11 JUN 26

Warranty Date: 11 JUN 26

Date In: 09 JUN 26

Time In:

Job #1 - Warranty

COMPLAINT: AC AND FURNACE INOP

CAUSE: The thermostat was showing error code e3. And the system was stagnit.

CORRECTION: Pulled down the cover and checked the wiring .power supply wire was loose in the wire nut.
Rewired and ran ac ..it turn on runs now .letting unit get cool enough to test the furnace for operation.
1.00HRS

Labor

Job #	Description	Total
1	DIAG AC	N/C
Subtotal for Job #1:		0.00

Job #2 - Internal

COMPLAINT: MISSING TPMS

CAUSE: Tmps was missing from unit

CORRECTION: Pulled 1 from unit stock number 9509

Labor

Job #	Description	Total
2	MULTIPLE LABOR CODES	N/C

Other Services

Code	Description	Qty	Price	Total
SS-I	SHOP SUPPLIES - INTERNAL	1.00	N/C	N/C
Subtotal for Job #2:				0.00

Job #3 - Internal

COMPLAINT: FRONT CAP "TRACER" BADGE PEELING

CAUSE: Front cap deal peeling on all letters

CORRECTION: Took pictures , clocked out
LEAVE AS IS

Customer #: 1000
MYERS "RV" CENTER,
INC.,



W/O: 73521
Promised Date: 11 JUN 26



Customer #: 1000
MYERS "RV" CENTER,
INC.,



Labor		
Job #	Description	Total
3	TRACER DECAL	N/C
Subtotal for Job #3:		0.00

Job #4 - Internal

COMPLAINT: NOISY FAN IN FREEZER

CAUSE: Fan was noisy in a unit 9608

CORRECTION: Pulled fan out of 12 volt fridge in unit number 9635

Labor		
Job #	Description	Total
4	FREEZER FAN	N/C
Subtotal for Job #4:		0.00

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	0.00

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 25 Jun 2026

