



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73115
Promised Date:
no add 26



WO #: 73115

Customer Name: 1000 - MYERS "RV"
CENTER, INC.

Completed Date: 24 JUN 26

Invoice#:

Author: BRIAN

Stock Desc: 9575 2026 SANIBEL
38LAUNDRY

Serial#: 5ZT3SN3B7TG706104

Chassis#: 5ZT3SN3B7TG706104

Miles/Hrs:

Tag#:

Purchased Date: 26 MAR 26

Warranty Date: 26 MAR 26

Date In: 30 MAR 26

Time In:

Job #0 - Warranty

CLAIM: 2625454

Subtotal for Job #0: 0.00

Job #1 - Warranty

COMPLAINT: SLIDES BLOW 30AMP FUSE / Factory rep here to witness issue.

CAUSE: DEFECTIVE MOTOR

CORRECTION: 2 main slides blowing 30 amp fuses going in and out

Check voltage in breaker box all voltage was correct

Unscrewed control board from the wall

Found the wire nuts and wires inside were not installed ccorrectly

Replaced both crimp wire nuts

Tested amp draw on the slides going in and out

Operating amps drivers side 17

End point in or out spiked at 37 then 67

Passenger side operating amp 15 end point spike 31

Determined the driver side slide motor was bad

Opened the bottom board found the motor was very rusty

Removed motor

Removed motor from stock unit 9574

Installed motor and retested amp draw on both slides

Drivers side operating 12 end point amp was 22 with a brief spike at 31

Passenger side operating at 13-15 amps end point 22 amps

Put the control back on the wall

Repaired bottom board

Work completed

Replacement motor arrived for the stock unit. Took the replacement motor to the stock unit and begin the installation process found the bolt holes did not lineup and the key for the actual slide control was not matching man lining up retrieve the old motor or the motor that I have gone bad discovered that the wrong slide motor had been shipped this will be on hold for new parts.

Correct motor arrived came assembled with an actuator.

New parts were fully installed. Did use two butts slices to connect the power. Used 5 feet of belly board tape to tape the cut in the bottom board. The work is now complete.

Labor

Job #	Description	Total
1	SLIDE OUT ROOM DIAGNOSTIC TIME	570.00

Customer #: 1000
MYERS "RV" CENTER,
INC.,





Customer #: 1000
 MYERS "RV" CENTER,
 INC.,



Parts

Part #	Description	Qty	Price	Total
10F14827A	ACTUATOR W/ MOTOR FOR VENTURE SLIDE ROOM 40" 18:1 HIGH SPEED	1.00	1,184.80	1,184.80

Other Services

Code	Description	Qty	Price	Total
FRT	SHIPPING & HANDLING CHARGES	1.00	17.25	17.25
FRT	SHIPPING & HANDLING CHARGES	1.00	56.69	56.69

Subtotal for Job #1: 1,828.74

Job #2 - Internal

SWAPPED MOTORS FROM STOCK UNIT 9574

Labor

Job #	Description	Total
2	SLIDE OUT ROOM DIAGNOSTIC TIME	N/C

Subtotal for Job #2: 0.00

Parts Total: 1,184.80

Labour Total: 570.00

Sublet Total: 0.00

Extras Total: 73.94

WORK ORDER TOTAL: 1,828.74

NOTICE:

DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 24 Jun 2026

