

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106
BASDEN RV CENTER INC
DBA AMERICAN RV CENTER
600 E BASELINE ROAD

EVANSVILLE, IN 47725
USA

Labor rate: \$150.00
OWNER INFORMATION

CLAIM STATUS Authorized
CLAIM 976549
CLAIM ORIGIN WEB
ORIGINAL CLAIM ID
VIN 4X4TCKY28NK082426
CHASSIS VIN
MILEAGE 0
SITE/WAREHOUSE 094 / 094A
ITEM # CKT23MK-94
DEALER RO # 66854
CLAIM START DATE 03/25/2022
CLAIM END DATE 01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor
Line# 1 **Operation Code** **Operational Description**
40-196-24-11-001297 Interior 12 Volt Wiring - Electrical/12 Volt Interior/Repair/Electrical
Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2022-03-25 14:48:53 :: AWNING ROLLED OUT 2 FEET AND STOPPED WHEN DOING CHECK IN AND HAD TO BE ZIP TIED IN, CHECK AND FIND PROBLEM AWNING ROLD OUT 2 FEET THEN STOPPED AND WOULDNT MOVE FOUND BAD CONNECTION ON INSIDE AT CONTROL PANEL CAUSING IT NOT TO FUNCTION PROPERLY AND REATTACJHECTED IT TO PANEL
Model # **Dlr Sub Hrs** 0.40 **Sub Labor Amt** \$60.00
Serial # **Appr Hrs** 0.40 **Appr Labor Amt** \$60.00
Notes
thank you

Labor
Line# 2 **Operation Code** **Operational Description**
60-141-19-00-001596 Tub Surround - Plumbing/Shower, Tub Surround/Reseal/No Tread Code
Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2022-03-25 14:52:02 :: SHOWER LEAKS EVERYWHERE ON SURROUND WHEN RUNING SHOWER WATER WOULD LEAK OUT AROUND THE SURROUND TOWARDS THE BEDROOM DOOR SEALED THE GAP AROUND THE SEAL
Model # **Dlr Sub Hrs** 0.40 **Sub Labor Amt** \$60.00
Serial # **Appr Hrs** 0.30 **Appr Labor Amt** \$45.00
Notes
time adjusted per flat rate

Submitted	Labor Amt	\$120.00	Approved	Labor Amt	\$105.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$120.00		Total	\$105.00

DEALER DATE
SIGNATURE
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER DATE
SIGNATURE
All repairs described have been inspected and are satisfactory.