



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

WO #: 27257

Customer: 47602 - TRI-AM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11321

Stock Desc: 2027 TT KZ-RV CONNECT 271RL

Model: 271RL

Serial #: 4EZTL2821V4053472

Chassis #:

Mileage: 0

Key #:

Req'n #: 62913

License #:

Trim:

Purchase Date:

Date In: 04 JUN 26

Promise Date:

Promise Time:

Schedule Date:

Completed: 24 JUL 26

Warr. Date: 26 JUN 26

Job #1 - Warranty

COMPLAINT: DOOR SIDE COMPARTMENT DOOR HAS CHIPS ON THE INSIDE, SMALL HOLES

CAUSE: NOTED ON DAF

CORRECTION: REPLACE COMPARTMENT DOOR AND RESEAL AREA IF NEEDED

LABOR .50

Labor

Job #	Description	Hours	Total
1	REPLACED COMPARTMENT DOOR	0.50	87.50

Parts

Part #	Description	Qty	Price	Total
167910	DOOR BAG RAD PW TH 24X32	1.00	116.96	116.96
79233	BUTYL TAPE 1/8X3/4	1.00	10.11	10.11

Subtotal for Job #1: 214.57

Job #2 - Warranty

COMPLAINT: SLIDE OUT STILE HAS SEVERAL NAIL HOLES ACROSS IT

CAUSE: NOTED ON DAF

NAIL HOLES NOT FILLED AND BLENDED AT BUILD

CORRECTION: FILL, COLOR AND BLEND AREA

LABOR .20

Labor

Job #	Description	Hours	Total
2	FILL COLOR AND BLEND	0.10	17.50

Subtotal for Job #2: 17.50

Job #3 - Warranty

COMPLAINT: PAINT FADED ACROSS THE TOP OF BENCH SEATING

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA

LABOR .20

W/O: 27257



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Labor			
Job #	Description	Hours	Total
3	FILL AND COLOR BLEND	0.50	87.50
Subtotal for Job #3:			87.50

Job #4 - Warranty

COMPLAINT: KITCHEN CABINETS ABOVE THE SINK DON'T SHUT ALL THE WAY ON ONE SIDE

CAUSE: NOTED ON DAF

CORRECTION: ADJUST HINGE ON DOOR TO OPEN AND CLOSE CORRECTLY

LABOR .30

Labor			
Job #	Description	Hours	Total
4	ADJUSTED HINGE	0.10	17.50
Subtotal for Job #4:			17.50

Job #5 - Warranty

COMPLAINT: BROWN STAINS ON THE CEILING AS YOU ENTER THE UNIT

CAUSE: NOTED ON DAF

CORRECTION: CLEAN SPOTS AND COLOR BLEND IF NEEDED

LABOR .30

THIS LINE WAS DENIED BY KZ

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: HALL VALANCE IS LOOSE ON THE WALL IN HALL WAY AREA

CAUSE: NOTED ON DAF

CORRECTION: RESECURE VALANCE BACK IN PLACE CORRECTLY

LABOR .10

Labor			
Job #	Description	Hours	Total
6	RESECURED VALANCE	0.10	17.50
Subtotal for Job #6:			17.50

Job #7 - Warranty

COMPLAINT: STILE ABOVE BEDROOM DOOR HAS A CHIPPED SPOT

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND TO MATCH

LABOR .20

CLAIM DENIED BY KZ

Subtotal for Job #7: 0.00

Job #8 - Warranty

COMPLAINT: BEDROOM DOOR IS DAMAGED AT THE TOP IN 2 PLACES

CAUSE: NOTED ON DAF

DAMAGED AT FACTORY INSTALL

CORRECTION: REPLACE THE BEDROOM DOOR

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

LABOR .50

Labor

Job #	Description	Hours	Total
8	REPLACED DOOR	0.50	87.50

Parts

Part #	Description	Qty	Price	Total
165594	DOOR,PASS,SPICE,1-3/8X28X76,2P,O FF,L&L	1.00	256.78	256.78

Other Services

Code	Description	Qty	Price	Total
CRA	CRATE CHARGES	1.00	50.00	50.00
FRT	FREIGHT ON PARTS	1.00	63.97	63.97

Subtotal for Job #8: 458.25

Parts Total: 383.85
Labour Total: 315.00
Sublet Total: 0.00
Extras Total: 113.97

WORK ORDER TOTAL: 812.82

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 24 Jul 2026

W/O: 27257



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

