



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

WO #: 27037

Customer: 47602 - TRI-AM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11223

Stock Desc: 2026 O FOREST RIVER CEDAR

CREEK 29RL

Model: 29RL

Serial #: 4X4FCRE23TS235365

Chassis #:

Mileage: 0

Key #:

Req'n #: 62814

License #:

Trim:

Purchase Date:

Date In: 21 APR 26

Promise Date:

Promise Time:

Schedule Date:

Completed: 23 JUN 26

Warr. Date:

Job #1 - Warranty

COMPLAINT: TECH SERVICE BULLETIN 20-1983

REAR WINDOWS

CAUSE: FOREST RIVER SENT NOTICE TO TRIAM ABOUT TSB 20-1983

CORRECTION: REMOVE CURRENT WINDOW, CLEAN WINDOW OPENING, APPLY FOAM TAPE AND
INSTALL NEW WINDOW

LABOR 2.0

Labor

Job #	Description	Hours	Total
1	REPALCED WINDOW	1.00	175.00

Parts

Part #	Description	Qty	Price	Total
F100815072	WINDOW, SQUARE, 72" X 40" X 21", FRAMELESS, 4000 SERIES INSULATED, G20, SVSE FIXED TOP, BOTTOM LEFT VENT, BOTTOM RIGHT VENTING EGRESS, EXIT WINDOW W/SHADE KIT TP BK V#V001120191	1.00	1,473.45	1,473.45
79233	BUTYL TAPE 1/8X3/4	2.00	10.11	20.22

Other Services

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	236.10	236.10
CRA	CRATE FEE, STANDARD, X6	6.00	65.00	390.00

Subtotal for Job #1: 2,294.77

Job #2 - Warranty

COMPLAINT: TECH SERVICE BULLETIN 20-1983

THIS IS DOOR SIDE REAR WINDOW

CAUSE: FOREST RIVER SENT NOTICE TO TRIAM ABOUT TSB 20-1983

CORRECTION: REMOVE CURRENT WINDOW, CLEAN WINDOW OPENING, APPLY FOAM TAPE AND
INSTALL NEW WINDOW

LABOR 2.0

W/O: 27037



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Labor			
Job #	Description	Hours	Total
2	REPLACED WINDOW	1.00	175.00

Parts				
Part #	Description	Qty	Price	Total
F100815074	WINDOW, SQUARE, 24" X 40" X 17", FRAMELESS, 4000 SERIES INSULATED, G20, SV FIXED TOP, VENTED BOTTOM, W/SHADE KIT, TP BK V#V001028050	1.00	684.96	684.96

Subtotal for Job #2: 859.96

Job #3 - Warranty

COMPLAINT: TECH SERVICE BULLETIN 20-1983
THIS IS REAR WINDOW ON DS SLIDE OUT

CAUSE: FOREST RIVER SENT NOTICE TO TRIAM ABOUT TSB 20-1983

CORRECTION: REMOVE CURRENT WINDOW, CLEAN WINDOW OPENING,APPLY FOAM TAPE AND
INSTALL NEW WINDOW
LABOR 2.0

Labor			
Job #	Description	Hours	Total
3	REPALCED WINDOW	1.00	175.00

Parts				
Part #	Description	Qty	Price	Total
F100815154	WINDOW, SQUARE, 54" X 40" X 17", FRAMELESS, 4000 SERIES INSULATED, G20, SVD FIXED TOP, BOTTOM LEFT AND RIGHT VENTS, W/SHADE KIT TP BK V#V001170473	1.00	1,177.64	1,177.64

Subtotal for Job #3: 1,352.64

Job #4 - Warranty

COMPLAINT: TECH SERVICE BULLETIN 20-1983
FRONT WINDOW ON DS SLIDE

CAUSE: FOREST RIVER SENT NOTICE TO TRIAM ABOUT TSB 20-1983

CORRECTION: REMOVE CURRENT WINDOW, CLEAN WINDOW OPENING,APPLY FOAM TAPE AND
INSTALL NEW WINDOW
LABOR 2.0

Labor			
Job #	Description	Hours	Total
4	REPLACED WINDOW	1.00	175.00

Parts				
Part #	Description	Qty	Price	Total
F100815154	WINDOW, SQUARE, 54" X 40" X 17", FRAMELESS, 4000 SERIES INSULATED, G20, SVD FIXED TOP, BOTTOM LEFT AND RIGHT VENTS, W/SHADE KIT TP BK V#V001170473	1.00	1,177.64	1,177.64

Subtotal for Job #4: 1,352.64

Job #5 - Warranty

COMPLAINT: TECH SERVICE BULLETIN 20-1983
DS FRONT CAP WINDOW

Customer #: 47602
TRIAM RV CENTER-EAST
TN,

CAUSE: FOREST RIVER SENT NOTICE TO TRIAM ABOUT TSB 20-1983

CORRECTION: REMOVE CURRENT WINDOW, CLEAN WINDOW OPENING,APPLY FOAM TAPE AND
INSTALL NEW WINDOW
LABOR 2.0

Labor

Job #	Description	Hours	Total
5	REPLACED WINDOW	1.00	175.00

Parts

Part #	Description	Qty	Price	Total
F100815153	WINDOW, 30" X 26", VEPW FRAMELESS, 4000 SERIES, INSULATED, G20, VENTED EGRESS, TP BLK W/ SHADE V#V000918114	1.00	454.94	454.94

Subtotal for Job #5: 629.94**Job #6 - Warranty**

COMPLAINT: TECH SERVICE BULLETIN
NDS REAR WINDOW

CAUSE: FOREST RIVER SENT NOTICE TO TRIAM ABOUT TSB 20-1983

CORRECTION: REMOVE CURRENT WINDOW, CLEAN WINDOW OPENING,APPLY FOAM TAPE AND
INSTALL NEW WINDOW
LABOR 2.0

Labor

Job #	Description	Hours	Total
6	REPLACED WINDOW	1.00	175.00

Parts

Part #	Description	Qty	Price	Total
F100815074	WINDOW, SQUARE, 24" X 40" X 17", FRAMELESS, 4000 SERIES INSULATED, G20, SV FIXED TOP, VENTED BOTTOM, W/SHADE KIT, TP BK V#V001028050	1.00	684.96	684.96

Subtotal for Job #6: 859.96

Parts Total: 5,673.81
Labour Total: 1,050.00
Sublet Total: 0.00
Extras Total: 626.10

WORK ORDER TOTAL: 7,349.91

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 23 Jun 2026

Customer #: 47602
TRIAM RV CENTER-EAST
TN,