



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 27226



WO #: 27226

Customer: 47602 - TRI-AM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11319

Stock Desc: 2026 TT KEYSTONE CROSSFIRE
2290BH

Model: 2290BH

Serial #: 4YDTBLK22TD432123

Chassis #:

Mileage: 0

Key #:

Req'n #: 62839

License #:

Trim:

Purchase Date:

Date In: 28 MAY 26

Promise Date:

Promise Time:

Schedule Date:

Completed: 02 JUL 26

Warr. Date:

Job #1 - Warranty

COMPLAINT: SEAM TAPE OVER THE DINING TABLE IS DOWN

CAUSE: NOTED ON DAF

CORRECTION: RESECURE BACK IN PROPER PLACE

LABOR .10

Labor

Job #	Description	Hours	Total
1	RESECURED	0.10	17.50
Subtotal for Job #1:			17.50

Job #2 - Warranty

COMPLAINT: BATHROOM MED CABINET HAS SPOTS LIKE GLUE ON THEM

CAUSE: NOTED ON DAF

CORRECTION: CLEAN AND COLOR BLEND AREA

LABOR .20

Labor

Job #	Description	Hours	Total
2	CLEANED AND COLOR	0.20	35.00
Subtotal for Job #2:			35.00

Job #3 - Warranty

COMPLAINT: LEFT SIDE OF SLIDE FASCIA IS STAINED

CAUSE: NOTED ON DAF

CORRECTION: CLEAN, COLOR AND BLEND AREA

LABOR .20

Labor

Job #	Description	Hours	Total
3	CLEANED AND COLOR	0.20	35.00

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Subtotal for Job #3: 35.00

Job #4 - Warranty

COMPLAINT: BOTTOM SHELF KITCHEN PANTRY IS SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA
LABOR .20**Labor**

Job #	Description	Hours	Total
4	FILL AND COLOR	0.20	35.00

Subtotal for Job #4: 35.00

Job #5 - Warranty

COMPLAINT: INSIDE BEDROOM DOORS SCRATCHED ON BOTH DOORS

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA
LABOR .20**Labor**

Job #	Description	Hours	Total
5	FILL AND COLOR	0.40	70.00

Subtotal for Job #5: 70.00

Job #6 - Warranty

COMPLAINT: BLACK MARKS ON WHITE WALL IN BEDROOM

CAUSE: NOTED ON DAF

CORRECTION: CLEAN AND COLOR BLEND AREA
LABOR .20**Labor**

Job #	Description	Hours	Total
6	CLEAN AND COLOR	0.20	35.00

Subtotal for Job #6: 35.00

Job #7 - Warranty

COMPLAINT: QUICK CONNECT SPRAY PORT OUTER DOOR MISSING

CAUSE: MISSING ON UNIT AT DELIVERY

CORRECTION: REPLACE QUICK CONNECT SPRAY PORT
LABOR .30**Labor**

Job #	Description	Hours	Total
7	REPLACED	0.30	52.50

Parts

Part #	Description	Qty	Price	Total
507780	EXTERIOR QUICK CONNECT SPRAY PORT	1.00	8.28	8.28

Other Services

Code	Description	Qty	Price	Total
SHF	SHIPPING/FREIGHT FEE	1.00	15.95	15.95

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

Subtotal for Job #7: 76.73

W/O: 27226

Parts Total: 8.28

Labour Total: 280.00

Sublet Total: 0.00

Extras Total: 15.95

WORK ORDER TOTAL: 304.23

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 02 Jul 2026



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

