



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26962



WO #: 26962

Customer: 47602 - TRI-AM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11288

Stock Desc: 2026 TT FOREST RIVER

ROCKWOOD SIGN 8339FK

Model: 8339FK

Serial #: 4X4TRLN21T1910862

Chassis #:

Mileage: 0

Key #:

Req'n #: 62835

License #:

Trim: 8336BH

Purchase Date:

Date In: 08 APR 26

Promise Date:

Promise Time:

Schedule Date:

Completed: 14 JUL 26

Warr. Date:

Job #1 - Warranty

COMPLAINT: NDS MIDDLE COMPARTMENT DOOR NOT CLOSING CORRECTLY, DOOR IS HITTING ON THE LEFT SIDE

CAUSE: NOTED ON DAF

COMPARTMENT DOOR IS OUT ADJUSTMENT

CORRECTION: ADJUST COMPARTMENT DOOR

LABOR .40

Labor

Job #	Description	Hours	Total
1	ADJUSTED COMP DOOR	0.40	70.00

Subtotal for Job #1: 70.00

Job #2 - Warranty

COMPLAINT: AWNING ARM LEFT SIDE IF LOOKING AT IT HAS A PAINT CHIP ON IT

CAUSE: NOTED ON DAF

CHIPPED AT FACTORY INSTALL

CORRECTION: REMOVE AND REPLACE AWNING ARM WITH NEW ONE

LABOR 1.0

Labor

Job #	Description	Hours	Total
2	REPAIR TOUCH UPS	1.00	175.00

Subtotal for Job #2: 175.00

Job #3 - Warranty

COMPLAINT: CABINET DOOR TO THE RIGHT OF KITCHEN SINK IS VERY LOOSE AT BOTTOM

CAUSE: NOTED ON DAF

CORRECTION: HINGE NEEDS TO BE ADJUSTED

LABOR .20

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: CABINET DOOR TO THE LEFT OF KITCHEN SINK HINGE IS LOOSE AT THE BOTTOM

CAUSE: NOTED ON DAF

CORRECTION: HINGE NEEDS TO BE ADJSUTED
LABOR .20

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: THE CABINET STILE BELOW KITCHEN COUNTER HAS A FADED AREA

CAUSE: NOTED ON DAF

CORRECTION: COLOR, FILL AND BLEND AREA
LABOR .20**Labor**

Job #	Description	Hours	Total
5	COLOR AND FILLED	0.20	35.00

Subtotal for Job #5: 35.00

Job #6 - Warranty

COMPLAINT: CEILING STRIP IN KITCHEN HAS BROWN STICKY SPOTS ON ONE END

CAUSE: NOTED ON DAF
DONE AT FACTORY INSTALLCORRECTION: CLEAN AND COLOR AREA
LABOR .10**Labor**

Job #	Description	Hours	Total
6	CLEAN AND COLOR	0.10	17.50

Subtotal for Job #6: 17.50

Job #7 - Warranty

COMPLAINT: TOP FASCIA ON KITCHEN SLIDE HAS A CHIPPED AREA

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA
LABOR .20**Labor**

Job #	Description	Hours	Total
7	FILL AND COLOR	0.30	52.50

Subtotal for Job #7: 52.50

Job #8 - Warranty

COMPLAINT: HOLES ON THE KITCHEN SLIDE FASCIA

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA
LABOR .10Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

Labor

Job #	Description	Hours	Total
8	FILLED AND COLOR	0.30	52.50
Subtotal for Job #8:			52.50

Job #9 - Warranty

COMPLAINT: BLACK MARKS ON WALL IN LIVING AREA

CAUSE: NOTED ON DAF

CORRECTION: CLEAN AND COLOR BLEND AREA

LABOR .10

Labor

Job #	Description	Hours	Total
9	COLOR AND FILL	0.20	35.00
Subtotal for Job #9:			35.00

Job #10 - WarrantyCOMPLAINT: STILE ON TOP OF KITCHEN ISLAND ALL ACROSS TOP IS DAMAGED
AREA IS SCRATCHEDCAUSE: NOTED ON DAF
DAMAGED AT FACTORY INSTALLCORRECTION: REMOVE AND REINSTALL COUNTER TOP TO ACCESS THE DAMAGED STILE
REMOVE STILE AND REPLACE WITH NEW
LABOR 3.5**Labor**

Job #	Description	Hours	Total
10	REPLACED STILE	3.50	612.50

Parts

Part #	Description	Qty	Price	Total
F100582610	STILE - PFL: SQUARE EDGE - ANDOVER SABLE - 2" X 8' - V# 47090001 X	1.00	8.65	8.65

Other Services

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	60.71	60.71
SPK	SPECIAL PACKAGING	1.00	13.00	13.00

Subtotal for Job #10: 694.86

Job #11 - Warranty

COMPLAINT: STILE ON THE SIDE OF THE KITCHEN ISLAND IS SCRATCHED

CAUSE: NOTED ON DAF
DAMAGED AT INSTALLCORRECTION: REPLACE STILE BOARD WHILE COUNTER TOP IS OFF ON LINE 10
LABOR 1.0**Labor**

Job #	Description	Hours	Total
11	REPLACED STILE	0.50	87.50

Parts

Part #	Description	Qty	Price	Total
F100582613	STILE - PFL: SQUARE EDGE - ANDOVER SABLE - 4" X 8' - V# 47090003 X	1.00	16.21	16.21

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

Subtotal for Job #11: 103.71

Job #12 - Warranty

COMPLAINT: HOLE IN WALL ABOVE PANEL CABINET

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA

LABOR .10

Labor

Job #	Description	Hours	Total
12	FILLED AND COLOR BLEND	0.20	35.00

Subtotal for Job #12: 35.00

Job #13 - Warranty

COMPLAINT: VALANCE OVER WINDOW IN LIVING HAS GREASE ON MATERIAL

CAUSE: NOTED ON DAF

CORRECTION: REMOVE VALANCE AND CLEAN MATERIAL THEN REINSTALL

LABOR .30

Labor

Job #	Description	Hours	Total
13	REMOVED VALANCE AND CLEANED MATERIAL	0.30	52.50

Subtotal for Job #13: 52.50

Job #15 - Warranty

COMPLAINT: BEDROOM DOOR FRAME HAS SEVERAL HOLES IN STILE

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND

LABOR .20

Labor

Job #	Description	Hours	Total
15	FILLED AND COLOR BLENDED	0.20	35.00

Subtotal for Job #15: 35.00

Job #16 - Warranty

COMPLAINT: STILE ACROSS THE BOTTOM OF THE HEAD BOARD IN BEDROOM IS SCRATCHED

CAUSE: NOTED ON DAF

DAMAGED AT INSTALL

CORRECTION: REMOVE DAMAGED STILE AND REPLACE WITH NEW

LABOR 1.5

Labor

Job #	Description	Hours	Total
16	REMOVED AND REPLACED STILE	1.50	262.50

Parts

Part #	Description	Qty	Price	Total
20G25284	IHO: WIDE/TALL HEADBOARD, PRINT #20G25284, ANDOVER SABLE, 2026	1.00	75.84	75.84

Other Services

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	227.64	227.64

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

Subtotal for Job #16: 565.98

W/O: 26962

Job #17 - Warranty

COMPLAINT: VENT ON BEDROOM CEILING IS BROKEN

CAUSE: NOTED ON DAF

CORRECTION: REPLACE VENT
LABOR .10

Labor

Job #	Description	Hours	Total
17	REPLACE VENT	0.10	17.50

Parts

Part #	Description	Qty	Price	Total
F100352944	A/C PART - PFL: CEILING VENT, ROUND - POLAR WHITE - 5" - V# 501-016-00002	1.00	2.18	2.18

Subtotal for Job #17: 19.68

Job #18 - Warranty

COMPLAINT: AWNING FABRIC HAS A HOLE IN IT

CAUSE: NOTED ON DAF

CORRECTION: REPLACE THE AWNING FABRIC
LABOR 1.5

Labor

Job #	Description	Hours	Total
18	REPAIRED AWNING FABRIC	0.50	87.50

Parts

Part #	Description	Qty	Price	Total
F100315284	AWNING PART - 7B-3: FLAMMABLE VIBRA-TITE AWINING REPAIR COMPOUND - BLACK - V# 2021011778	1.00	81.34	81.34

Subtotal for Job #18: 168.84

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

Parts Total: 184.22
Labour Total: 1,627.50
Sublet Total: 0.00
Extras Total: 301.35
WORK ORDER TOTAL: 2,113.07

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 14 Jul 2026