

Pre-Authorization

Pre-Authorization number PA03087366 Reference no: 66934 Status: Approved Approved by stuml Approved date 4/7/2022

Servicing Name Address VIN Retail sold on Dealer

1194 Basden's American RV Basden's American RV 4YDT28029M3104978 10/9/2020
600 E Baseline Rd
Evansville, IN 47725

Nu mbe r of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	2102808B	Wall - Metal Siding	0.00	20.00			1	0.50	Complaint:THE SIDING IS COMING DETACHED FROM THE OFF DOOR FRONT SIDE NEAR THE TOP Cause:INSTALLED IMPROPERLLY AND BALLOONED AFTER INSPECTING FOUND STAPLES DID NOT HOLD SO THE WIND CAUGHT IT AND DAMAGED IT. Correction:REMOVE FRONT TRIM. REMOVE REAR TRIM. REMOVE SEALS AROUND SLIDEROOM. REMOVE GUTTER. REMOVE WINDOW. THAN REMOVE AND REPLACE DAMAGED METAL. KRV- Moved to PA03090694 as structural
2	2103416A	Slide Out - Box - I	0.00	0.40	0.20		1	0.10	Complaint:THE TRIM FROM THE REAR SIDE CEILING OF THE SLIDE ROOM FELL DOWN Cause:Improperly Installed Correction:REMOVED NAILS AND STAPLED BACK TRIM AND FILLED HOLES WITH PUTTY KRV – Labor time adjusted allowing for proper repair procedure to be performed.
3	3202012A	Panel - Interior Wi	0.00	0.40	0.30		1	0.10	Complaint:SOME OF THE STAPLES ARE COMING OUT OF THE PANELING IN THE BEDROOM Cause:Improperly Installed Correction:REMOVED WALL TAPE AND STAPLED BACK PANELS KRV – Labor time adjusted allowing for proper repair procedure to be performed.
4	3201516A	Batten Strips & Cr	0.00	0.40	0.10		1	0.10	Complaint:SOME OF THE PANELING ON THE STORAGE ABOVE THE BED IS LOOSE Cause:Improperly Installed Correction:STAPLED BACK TRIM ABOVE BED AND PUTTY HOLES KRV – Labor time approved and adjusted in accordance with Keystone RV's flat rate manual.

For paper claims only use one pre-authorization number per warranty claim for

Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company

Pre-Authorization

Nu	Root	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
		mbe operation							
		r of							
Pre-Authorization number PA03087366					0.60				

For paper claims only use one pre-authorization number per warranty claim for
 Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company