



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

Estimate: 27341 HENSLEY, AMANDA



Estimate: 27341 (Appointment Date: 22 JUN 2026 - Time: 11:00am)

Customer: 90276 - HENSLEY, AMANDA
Address: 3820 JONES BRIDGE RD
GREENEVILLE, TN
37743

Home Phone: 678-378-0604

Work Phone:

Author: TJH

Location: IH

Invoice #:

Stock #:
Stock Desc: 2021 TT KEYSTONE SPRINTER
330KBS
Model: 330KBS
Serial #: 4YDT33023M1532587
Chassis #:
Mileage: 0
Key #:
Req'n #: 62816
License #:
Trim:

Purchase Date:
Date In: 20 JUN 26
Promise Date: 30 JUL 26
Promise Time: 09:00am
Schedule Date:
Completed:
Warr. Date:

Job #1 - External

DEWIN MAKE SURE WE USE THE PUMP TO DEWIN

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1	0.00	0.00

Subtotal for Job #1: 0.00

Job #2 - External

CS THAT THE CAMERAS ARE INOP CHECK AND ADVISE

Subtotal for Job #2: 0.00

Job #3 - External

COMPLAINT: CS THAT THERE IS A LEAK AT THE BASE OF THE TOILET CHECK AND ADVISE

CAUSE: TOILET VALVE WHERE WATER LINE CONNECTS WAS ONLY HAND TIGHT

CORRECTION: TURNED VALVE TO TIGHTEN AND TESTED, NO FURTHER ISSUES AT THIS TIME

Subtotal for Job #3: 0.00

Job #4 - External

INSTALL BADAY ONTO TOILET

Subtotal for Job #4: 0.00

Job #ROOFINS - External

COMPLAINT: COMPLEMENTARY ROOF INSPECTION

CHECK CAULKING _____

CHECK SKYLIGHTS _____

CHECK ROOF VENTS _____

CHECK LUBE & ANTENNA _____

CHECK SATELLITE _____

CHECK RUBBER _____

CAUSE: RUBBER CAULK IS CRACKING ON THE SIDES, RECOMMEND SCRAPE AND SEAL



Subtotal for Job #ROOFINS: 0.00

Job #6 - External

COMPLAINT: WASH UNIT

CORRECTION: UNIT WASHED

Other Services

Code	Description	Qty	Price	Total
WASH	WASH COACH	0	200.00	0.00

Subtotal for Job #6: 0.00

Job #7 - External

COMPLAINT: BEARING REPACK

CORRECTION: BEARINGS REPACKED

Parts

Part #	Description	Qty	Price	Total
32533	5605 PKG/2 SEALS	0	15.99	0.00
BPC-20	BRAKE CLEANER	0	8.99	0.00

Subtotal for Job #7: 0.00

Job #5 - External

CS THAT THE BLACK TANK FLUSH IS NOT WORKING ACTS LIKE NO WATER IS COMING THROUGH INTO THE TANK

Subtotal for Job #5: 0.00

Job #8 - External

CS THAT THE FRIDGE ON THE ON THE RIGHT TAKES LONGER TO GET COLD THEN THE CHECK FRIDGE

Subtotal for Job #8: 0.00

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
Tax Total:	0.00
Estimate Total:	0.00

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 25 Jun 2026

