

BASDEN RV CENTER, INC D.B.A. AMERICAN RV  
 600 E. Baseline Rd.  
 Evansville IN  
 US  
 47725  
 812-867-5200

WORK ORDER # 66935

Completed : 04 APR 22                      Customer : 50956 - ZOPH, JAMES E. - 812-838-35  
 Licence # :                                      Invoice # :  
 Stock No : 10946                              Description : 2021 TT KEYSTONE SPRINGDALE 220RD  
           Tag :                                      Date In : 29 MAR 22                      Mileage :  
           Author : BJW                              Promised : 16 APR 22  
 Location : 0405 CHECK PREAUTH Date Sched :  
 Serial# : 4YDT22023M3112202              Chassis# : 4YDT22023M3112202  
 Warr. Date : 19 JUN 21                      Cust PO# :  
 Print Date : 04 APR 22

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
1      COMPLAINT:  CUSTOMER STATES THAT WHEN FILLING THE          I      SPN      SALES
      CORRECTION:  FRESH WATER TANK WATER SPURTS OUT.
      I FILLED THE FRESH TANK 3 TIMES AND IT
      WAS FULL WHEN IT GOT HERE. EVERY TIME I
      FILLED THE FRESH TANK, I USED A
      DIFFERENT HOSE FITTING. I COULD NOT GET
      THE WATER TO SPURT OUT UNLESS THE TANK
      GETS OVER FILLED.
2      COMPLAINT:  CUSTOMER STATES THAT THE THERMOSTAT IS          W      1013    KEYST
      CORRECTION:  ABOUT TO FALL OFF THE WALL.
      TIGHTENED THE THERMOSTAT SCREW AND ADDED
      A 2ND SCREW TO IT.
3      COMPLAINT:  CUSTOMER ADVISES THAT THE PUMP RUNS              W      1013    KEYST
      CORRECTION:  EVERY FEW SECONDS AND IT VIBRATES BADLY.
      CHECKED WATER PUMP AND FOUND THAT THE
      CHECK VALVE WAS NOT CLOSING INSIDE THE
      WATER PUMP. I REMOVED THE PUMP AND TOOK
      IT APART. I FOUND PLASTIC TRIMMINGS
      INSIDE THE PUMP. I CLEANED ALL OF THE
      TRIMMINGS OUT OF THE PUMP AND
      REINSTALLED IT. TESTED PUMP AGAIN AND IT
      IS NOW WORKING AS IT SHOULD.
```

```
*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
1  Z990  MISCELLANEOUS REPAIR  GAH  I-SPN  0.00  25.00  0.00
1  Z990  MISCELLANEOUS REPAIR  GAH  I-SPN  0.73  25.00  18.25
1  Z990  MISCELLANEOUS REPAIR  GAH  I-SPN  0.08  25.00  2.00
1  Z990  MISCELLANEOUS REPAIR  GAH  I-SPN  0.19  25.00  4.75
2  Z990  MISCELLANEOUS REPAIR  GAH  W-1013  0.03  150.00  4.50
2  Z990  MISCELLANEOUS REPAIR  GAH  W-1013  0.27  150.00  40.50
3  Z990  MISCELLANEOUS REPAIR  GAH  W-1013  0.00  150.00  0.00
3  Z990  MISCELLANEOUS REPAIR  GAH  W-1013  0.50  150.00  75.00
```

Continued on page 2

Work Order : 66935

```
*****
Job #  Excode  Description  EXTRAS      bill to  Qty  Price  Total
*****
   1  SS      SHOP SUPPLIES      I-SPN    1.00   0.00   0.00
*****
```

CUSTOMER COMMENTS

BH SENT IN PREAUTH

BILLINGS SUMMARY

```
*****
Type Bill Id      Parts  Labour  Sublet  Extras  Tax  Total
*****
I   SPN           0.00   25.00   0.00   0.00   0.00   25.00
W   1013          0.00  120.00   0.00   0.00   0.00  120.00

Totals           0.00  145.00   0.00   0.00   0.00  145.00
*****
```