



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

Estimate: 27321 MAUD, VINNY



Estimate: 27321 (Appointment Date: 23 JUN 2026 - Time: 11:00am)

Customer: 87885 - MAUD, VINNY
Address: 85 STERLING DR
MOSHEIM, TN
37818

Home Phone: (203) 258-8548

Work Phone:

Author: CLP

Location: IH

Invoice #:

Stock #:
Stock Desc: 2019 TT GRAND DESIGN IMAGINE
2670MK
Model: 2670MK
Serial #: 573TE3227K6615846
Chassis #:
Mileage:
Key #:
Req'n #:
License #:
Trim:

Purchase Date:
Date In: 16 JUN 26
Promise Date:
Promise Time:
Schedule Date:
Completed:
Warr. Date:

Job #1 - External

cus has ext warranty

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1	0.00	0.00

Subtotal for Job #1: 0.00

Job #2 - External

cus states rear axle may be bent

Subtotal for Job #2: 0.00

Job #3 - External

cus has no water to rear of rv

Subtotal for Job #3: 0.00

Job #4 - External

awning rear arm is not closing all of the way check and advise

Subtotal for Job #4: 0.00

Job #5 - External

molding above door and slides on both sides needs to be tacked up

Subtotal for Job #5: 0.00

Job #6 - External

door slide has difficulty going out check and advise



Subtotal for Job #6: 0.00

Job #7 - External

wall next to recliner is flexible check and advise

Subtotal for Job #7: 0.00

Job #8 - External

awning still leaks above door check and advise

Subtotal for Job #8: 0.00

Job #9 - External

cus states awning hangs too low when opened all of the way check and advise

Subtotal for Job #9: 0.00

Job #10 - External

cus states oven will get to temp and never relight check and advise

Subtotal for Job #10: 0.00

Job #11 - External

cus states the rear right side of rv gets no water through quick connect check and advise

Subtotal for Job #11: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
Tax Total: 0.00
Estimate Total: 0.00

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 13 Jul 2026

