



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

WO #: 27162 (Appointment Date: 14 MAY 2026 - Time: 02:30pm)

Customer: 93143 - POPE, GREGORY
Address: 1144 ELIZABETHTON HWY
BLUFF CITY, TN
37618

Home Phone: 423-534-0403

Work Phone:
Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11017

Stock Desc: 2025 C FOREST RIVER FORESTER

3251DSLEF

Model: 3251DSLEF

Serial #: 1FDXE4FN0SDD26625

Chassis #: 1FDXE4FN0SDD26625

Mileage: 12121

Key #: 5299

Req'n #: 62912

License #:

Trim:

Purchase Date: 12 AUG 25

Date In: 14 MAY 26

Promise Date:

Promise Time:

Schedule Date:

Completed: 30 JUL 26

Warr. Date: 12 AUG 25

Job #3 - Warranty

COMPLAINT: WH is leaking at pop off check and advise

CORRECTION: TECHS VERIFIED THERE IS NO ISSUE AT THIS TIME, NO LEAK FOUND

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: CABINET DOOR ABOVE DINNETE ON RIGHT IS PEELING CHECK AND ADVISE

CAUSE: OVERLAY IS PEELING OFF CABINET DOOR

CORRECTION: REPLACE CABINET DOOR

REMOVE CABINET DOOR, REMOVE HARDWARE TO INSTALL ON NEW CABINET DOOR

LABOR .50

Labor

Job #	Description	Hours	Total
4	REPLACED CABINET DOOR	0.50	87.50

Parts

Part #	Description	Qty	Price	Total
F100431439	DOOR, DRAWER FRONT, 14" X 20" C2 MDF, BEVELED RAIL RIVER TEAK - GENESIS 0485260 SUNSEEKER / FORESTER STARTED 7/2023	2.00	20.80	41.60

Subtotal for Job #4: 129.10

Job #5 - Warranty

COMPLAINT: CABINET DOOR ABOVE DINNETE ON LEFT IS PEELING

CAUSE: OVERLAY IS PEELING OFF CABINET DOOR

CORRECTION: REPLACE CABINET DOOR

REMOVE CABINET DOOR, REMOVE HARDWARE TO INSTALL ON NEW CABINET DOOR

LABOR .50

Labor

Job #	Description	Hours	Total
5	REPLACED CABINET DOOR	0.50	87.50

Parts



Part #	Description	Qty	Price	Total
F100512400	DOOR, DRAWER FRONT, 10" X 27" FLAT, RIVER TEAK - GENESIS 0533051 SUNSEEKER / FORESTER STARTED 7/2023	1.00	22.49	22.49

Subtotal for Job #5: 109.99

Job #6 - Warranty

COMPLAINT: CABINET DOOR TO LEFT OF BATHROOM MIRROR IS PEELING CHECK AND ADVISE

CAUSE: OVERLAY IS PEELING OFF CABINET DOOR

CORRECTION: REPLACE CABINET DOOR

REMOVE CABINET DOOR, REMOVE HARDWARE TO INSTALL ON NEW CABINET DOOR

LABOR .50

Labor

Job #	Description	Hours	Total
6	REPLACED CABINET DOOR	0.50	87.50

Parts

Part #	Description	Qty	Price	Total
F100512449	DOOR, DRAWER FRONT, 13" X 27" FLAT, RIVER TEAK - GENESIS 0533066 SUNSEEKER / FORESTER STARTED 7/2023	1.00	30.67	30.67

Subtotal for Job #6: 118.17

Job #7 - Warranty

COMPLAINT: WINDOW BEHIND FRONT SLIDE IS LEAKING CAUSING THE BLIND TO DISCOLOR

CAUSE: SKYLIGHT IS CRACKED AND ALLOWING WATER TO LEAK INTO THE UNIT. THIS HAS DAMAGED THE INTERIOR WALL PANEL, SHADE AND BATTON.

CORRECTION: REMOVE SKYLIGHT, CLEAN AREA, REPLACE WITH NEW SKYLIGHT AND RESEAL AREA.

REMOVE AND REINSTALL WINDOW. REMOVE DAMAGED WALL PANEL AND BATTON, REPLACE WITH NEW. WILL NEED TO REMOVE AND REINSTALL THE CABINETS ON WALL, COUNTER TOP, KITCHEN FAUCET TO ACCESS THE DAMAED WALL PANEL.

WILL ALSO NEED TO REPLACE THE WINDOW SHADE AND VALANCE DUE TO WATER DAMAGE.

LABOR 10.0

Labor

Job #	Description	Hours	Total
7	REPLACED APPROVED PARTS AND REPAIRED AREA	8.00	1,400.00

Parts

Part #	Description	Qty	Price	Total
F100517489	VALANCE	1.00	52.13	52.13
F100220017	SHADE, NIGHT 20.5" X 23" NIGHT, SLATE ROCK (FT12) - MCD S24335 STARTED 54380 MBS AND TRANSIT STOPPED 65888	1.00	91.74	91.74
20X32637A	SKYLIGHT 22 X 30 SINGLE PANE RAISED FLAT OUTER CLEAR	1.00	64.86	64.86
F100363092	PANEL, 2.7MM X 48" X 102" 4 STAR LN HUNT CLOUD MAIN WALL - GENESIS 455478 STARTED 60843 - STOPPED 4/2025	1.00	52.40	52.40
20X44041A	ADHESIVE, 3M, 560, FAST CURE, WHITE, 10.5oz TUBE	1.00	10.21	10.21
38-9018	LAP SEALANT WHITE	3.00	10.21	30.63

W/O: 27162



Customer #: 93143
POPE, GREGORY



F100362907	MOLDING, FLAT BATTEN, 1" X 96" HUNT CLOUD 4 STAR - GENESIS 455471 STARTED 60843 - STOPPED 4/2025	1.00	2.42	2.42
------------	---	------	------	------

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT ON PARTS	1.00	281.20	281.20

Subtotal for Job #7: 1,985.59

Job #8 - Warranty

COMPLAINT: CABINET DOOR ABOVE ENTRY DOOR IS LEAKING CHECK AND ADVISE

CAUSE: OVERLAY IS PEELING OFF CABINET DOOR

CORRECTION: REPLACE CABINET DOOR
REMOVE CABINET DOOR, REMOVE HARDWARE TO INSTALL ON NEW CABINET DOOR
LABOR .50

PART WAS NOT ORDERED, ADDING TO ANOTHER CLAIM.

Subtotal for Job #8: 0.00

Parts Total:	399.15
Labour Total:	1,662.50
Sublet Total:	0.00
Extras Total:	281.20
WORK ORDER TOTAL:	2,342.85

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 30 Jul 2026

W/O: 27162



Customer #: 93143
POPE, GREGORY

