

Claim Response

Claim: C3056448

Last Modified by ambri

Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed warranty rate	Type	Date Of Purchase
C3056448	66973	4/8/2022	4/8/2022	4YDT26026M3110418		1194	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	150.00	0.00	SA21-414	5/8/2021

Deny code	Item number	Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
	692585	Regulator - Kit - Auto Change	1.00	0.00	48.79	15.00	56.11	0.00	0.00	0.00	Approved
5121839											
Component Model: 6020 Component Serial Number: N 19 50											
	446897	Hose - LP - 12" Pigtail	2.00	0.00	6.65	15.00	15.30	0.00	0.00	0.00	Approved

5121839

Deny code	Operation	Description	Srvc advisory	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	7141442B	Safety Advisory 21-414 Winn-Tec Complaint: KEYSTONE LP REGULATOR SERVICE CAMPAIGN Cause: BROKEN LP REGULATOR Correction: REPLACED LP REGULATOR WITH NEW ONE AND CHECKED FOR LEAKS. CUSTOMER DID NOT HAVE LP TANKS WITH UNIT SO USED TEST ONES (AP KBS)		0.50	0.50	75.00	0.00	1	0.50	Approved

Submitted parts & subLet 71.41
 Submitted labor & subLet 75.00
 Submitted freight: 0.00
 Tax: 0.00
 Total Submitted: 146.41

Approved parts & subLet 71.41
 Approved labor & subLet 75.00
 Approved freight: 0.00
 Tax: 0.00
 Total approved: 146.41