



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 66982

CUSTOMER WORK ORDER

WO #: 66982

Customer: 51850 - REV TR OF SALLY A
AND CRAIG E BECKLEY - 812-744-3848
Tag:
Author: BH
Location: 0421 CHECKWORK

Stock #: 11049
Stock Desc: 2022 5W KEYSTONE
COUGAR HALF-TON 23MLS
Chassis #: 4YDFCGK27NV507381
Serial #: 4YDFCGK27NV507381
Mileage: 0
Licence:

Invoice #:
Date In: 02 APR 22
Promised:
Date Sched:
Completed: 20 APR 22
Warr. Date: 08 APR 22

Job #PDINFW - Internal

COMPLAINT: PDI - NEW FIFTH WHEEL

CAUSE: PDINFW - PDI NEW FIFTH WHEEL.

CORRECTION: Moved unit into shop from sales lot. Purged and filled LP tanks. Installed (2) new batteries and connected together with cables. Checked all exterior lights and brakes. Checked lug nuts and set tire pressure at 80 psi. Recorded all tire serial numbers. Leveled unit manually and reseal auto leveling system. Checked roof and awning. Checked entrance door and all compartment doors. Checked power cord. Operated slide outs. Checked all interior lights. Checked all cabinets and drawers. Checked all windows and blinds. Checked all electrical outlets and GFCI outlets. Checked all USB outlet. Checked converter output. Removed all appliances packing. Installed a temp. Lp quick connect to check LP drop. Recorded all serial numbers and took pictures. Applied all company decals. Filled fresh water tank and flush antifreeze from water lines and faucets. Checked all water lines and faucets for leaks. Opened by-pass on water heater and filled. Purged all air from water system. Performed LP drop test and set LP pressure at 11 in.wc. Filled all holding tanks and checked monitor panel. Checked TV Antenna, TV and Radio DVD/CD player. Checked TV outlets in front bedroom and outside front compartment. Checked all appliances. Rplacd missing handle on galley tank dump valve.

Labor

Code	Description	Mechanic	Total
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	DKM	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	DKM	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	DKM	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	DKM	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	DKM	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
24478	VALVE HANDLE - METAL	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	12.00	N/C	N/C

Subtotal for Job #PDINFW: 0.00

Job #FPDINFW - Internal

COMPLAINT: FINAL PDI ON NEW FIFTH WHEELS

CAUSE: FPDINFW - FINAL PDI ON NEW FIFTH WHEEL.

CORRECTION: Drained all holding tanks. Retracted all electrical jacks. Closed slide outs. Water heater is



Customer #: 51850
REV TR OF SALLY A AND



full and ready to camp. Moved unit to wash bay area.

Labor

Code	Description	Mechanic	Total
PDINFW	FINAL PDI NEW FIFTH WHEEL (INTERNAL	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 D	2.00	N/C	N/C
5516	A10-3050FHVP 30M-50F PIGTAIL	1.00	N/C	N/C

Subtotal for Job #FPDINFW: 0.00

Job #1 - Internal

COMPLAINT: INSTALL SIDE WINDER

CORRECTION: INSTALLED SIDEWINDER PINBOX AND HOOKED UP TO TRUCK. ADJUSTED PIN BOX TO WORK WITH HITCH.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C

Parts

Part #	Description	Qty	Price	Total
5069	SIDEWINDER FOR LIP	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #WALK - Internal

COMPLAINT: WALK THRU

CORRECTION: PULLED CAMER FROM WASH BAY AND PUT IN WALK THRU AREA AND SET UP. close back up and bring back to shop to put on sidewinder hitch. SET BACK IN WALK THRU ARE AND SET UP DID WALK THRU AND SHOWED CUSTOMER SIDEWINDER HITCH AND BRAKE CONTROL.

Estimated Amount: 180.00

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C

Subtotal for Job #WALK: 0.00

Job #2 - Warranty

COMPLAINT: FRONT COMPATMENT DOOR HOLD BACK WON'T HOLD THE DOOR OPEN

CAUSE: FRONT COMPARTMENT DOOR HOLD BACK WON'T HOLD DOOR OPEN.

CORRECTION: Compartment door hold back not mounted in correct location to hold door open. Removed hold back and remounted to hold door open.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DKM	75.00

Subtotal for Job #2: 75.00

Job #3 - Warranty

COMPLAINT: CEILING TRIM BOWED OVER DINETTE



Customer #: 51850
REV TR OF SALLY A AND



CAUSE: CEILING TRIM BOWED OVER DINETTE.

CORRECTION: Dropped dinette table to lower position Placed a piece of panneling oved table to prevent damage. Used small step ladder to reach trim. Stapled trim back in place with brad nailer. Removed panel and replaced all cushions.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DKM	45.00

Subtotal for Job #3: 45.00

Parts Total: 0.00
 Labour Total: 120.00
 Sublet Total: 0.00
 Extras Total: 0.00
WORK ORDER TOTAL: 120.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 22 Apr 2022



Customer #: 51850
REV TR OF SALLY A AND

