
Claim 2702339 - Labor Line 4

Angie Espinas-Runyon <aespinas-runyon@forestriverinc.com>
To: Alix Mongiat <alix@dealer-advisors.com>
Cc: Michelle Antinoja <mgray@greenewayrv.com>

Fri, Jul 10, 2026 at 3:29 PM

Hi,

This was where you take the header off the door and use stacked drill bits like this to get the screw replaced.



The screws also need to come out of the top of the door that are holding the rollers in.

Remove the one here



Does this make sense? 😊

[Quoted text hidden]