

Claim Response

Claim: C3055978

Non-Warranty Goodwill Adjustment

Last Modified by C2275

Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed warranty rate	Type	Date Of Purchase
C3055978	67006	4/8/2022	4/8/2022	4YDT26025M3100656		1194	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	150.00	0.00	SA21-414	7/2/2020

Deny code	Item number	Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
	692585	Regulator - Kit - Auto Change	1.00	0.00	48.79	15.00	56.11	0.00	0.00	0.00	Parts Under Review
Component Model: 4020 Component Serial Number: N 20 03											
	446897	Hose - LP - 12" Pigtail	2.00	0.00	6.65	15.00	15.30	0.00	0.00	0.00	Parts Under Review

Deny code	Operation	Description	Srvc advisory	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	7141442B	Safety Advisory 21-414 Winn-Tec Complaint: KEYSTONE SAFETY ADVISORY LP REGULATOR RECALL #21-414 SECTION:71 COMPONENT:414 OPERATION:7141442B PART#380444 Cause: LP REGULATOR RECALL FOR SPRINGDALE Correction: REPLACED WITH NEW TYPE REGULATOR AND CHECKED FOR LEAKS		0.50		0.00	0.00	1	0.50	Pending approval

Submitted parts & subLet 71.41
Submitted labor & subLet 75.00
Submitted freight: 0.00
Tax: 0.00
Total Submitted: 146.41

Approved parts & subLet 0.00
Approved labor & subLet 0.00
Approved freight: 0.00
Tax: 0.00
Total approved: 0.00