

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106 BASDEN RV CENTER INC DBA AMERICAN RV CENTER 600 E BASELINE ROAD EVANSVILLE, IN 47725 USA Labor rate: \$150.00 OWNER INFORMATION	CLAIM STATUS Authorized CLAIM 993399 CLAIM ORIGIN WEB ORIGINAL CLAIM ID VIN 5ZT2CAUB0NX026077 CHASSIS VIN MILEAGE 0 SITE/WAREHOUSE 205 / 205 ITEM # ACAT293QBCKLE DEALER RO # 67009 CLAIM START DATE 04/08/2022 CLAIM END DATE 01/01/1900
--	--

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code 60-136-15-00-001499	Operational Description Water Line - Plumbing/Fresh Water Supply/Repair or Replace/No Tread Code Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-04-08 13:22:25 :: UNDER THE BATHROOM IT IS LEAKING REALLY BAD TURNED CITY WATER ON AND HEARD A POP. THE COLD LINE BATHROOM FAUCET HAD BURSTED OFF UE TO POORLY CONNECTION TO FITTING BAND FLODDED THE BATHROOM INSTALLED NEW CONE SEAL AND RE ATTACHED COLD LINE HOSE PROPERLY AND MADE SURE IT WAS TIGHT								
	Model # Serial #	<table border="0" style="width: 100%;"> <tr> <td style="width: 30%;">Dlr Sub Hrs</td> <td style="width: 10%;">1.00</td> <td style="width: 30%;">Sub Labor Amt</td> <td style="width: 30%;">\$150.00</td> </tr> <tr> <td>Appr Hrs</td> <td>0.50</td> <td>Appr Labor Amt</td> <td>\$75.00</td> </tr> </table>	Dlr Sub Hrs	1.00	Sub Labor Amt	\$150.00	Appr Hrs	0.50	Appr Labor Amt	\$75.00
Dlr Sub Hrs	1.00	Sub Labor Amt	\$150.00							
Appr Hrs	0.50	Appr Labor Amt	\$75.00							

Notes

excessive time requested per repair description

Labor

Line# 2	Operation Code 70-148-01-00-001714	Operational Description Radio Remote - Appliances/Radio/Replace/No Tread Code Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-04-08 13:26:20 :: FIREPLACE REMOTE MISSING MISSING REMOTE REPLACE REMOUNT								
	Model # Serial #	<table border="0" style="width: 100%;"> <tr> <td style="width: 30%;">Dlr Sub Hrs</td> <td style="width: 10%;">0.10</td> <td style="width: 30%;">Sub Labor Amt</td> <td style="width: 30%;">\$15.00</td> </tr> <tr> <td>Appr Hrs</td> <td>0.00</td> <td>Appr Labor Amt</td> <td>\$0.00</td> </tr> </table>	Dlr Sub Hrs	0.10	Sub Labor Amt	\$15.00	Appr Hrs	0.00	Appr Labor Amt	\$0.00
Dlr Sub Hrs	0.10	Sub Labor Amt	\$15.00							
Appr Hrs	0.00	Appr Labor Amt	\$0.00							

Notes

Part only NO labor

Labor

Line# 3	Operation Code 30-101-01-00-001081	Operational Description Sliding, Pocket Door Guide - Interior/Interior Doors/Replace/No Tread Code Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-04-08 13:29:04 :: BACK BEDROOM SLIDING DOOR STICKING DURING OPERATION BACK BEDROOM SLIDIND DOOR WAS STICKING ON BOTTOM TRACK GUIDE WHEN SLIDING ADJUSTDED THE BOTTOM SLIDING TRACK GUIDE								
	Model # Serial #	<table border="0" style="width: 100%;"> <tr> <td style="width: 30%;">Dlr Sub Hrs</td> <td style="width: 10%;">0.20</td> <td style="width: 30%;">Sub Labor Amt</td> <td style="width: 30%;">\$30.00</td> </tr> <tr> <td>Appr Hrs</td> <td>0.10</td> <td>Appr Labor Amt</td> <td>\$15.00</td> </tr> </table>	Dlr Sub Hrs	0.20	Sub Labor Amt	\$30.00	Appr Hrs	0.10	Appr Labor Amt	\$15.00
Dlr Sub Hrs	0.20	Sub Labor Amt	\$30.00							
Appr Hrs	0.10	Appr Labor Amt	\$15.00							

Notes

excessive time requested per repair description

Submitted	Labor Amt	\$195.00	Approved	Labor Amt	\$90.00
------------------	-----------	----------	-----------------	-----------	---------

