



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 67011
Promised Date: 30 APR 22

CUSTOMER WORK ORDER

WO #: 67011 (Appointment Date: 06 APR 2022 - Time: 07:00am)

Customer: 51342 - KEYS, KEVIN D. -
812-459-1628

Stock #: 10686

Stock Desc: 2021 TT COACHMEN

Invoice #:

Date In: 05 APR 22

Tag:

CATALINA 343BHTSLE

Promised: 30 APR 22

Author: BJW

Chassis #: 5ZT2CAZB4MX021858

Date Sched:

Location: 0513 SEE IF CUSTOMER HAS
SHOWN UP YET

Serial #: 5ZT2CAZB4MX021858

Completed: 13 MAY 22

Mileage: 0

Warr. Date: 14 MAY 21

Licence:

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES THAT SOME OF THE LED'S
UNDER THE AWNING HAVE WENT OUT

CORRECTION: REMOVED OLD LED LIGHTS AND INSTALLED NEW LED LIGHTS. THE PLASTIC
INSERT BROKE THAT HOLDS THE LED AND PART OF THE LED LIGHT SHORTED OUT

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	75.00

Parts

Part #	Description	Qty	Price	Total
F100247635	LED LIGHTS FOR CAR	1.00	137.91	137.91

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-LIGHTS	1.00	15.93	15.93

Subtotal for Job #1: 228.84

Job #2 - Internal

COMPLAINT: CUSTOMER STATES THAT THE AWNING IS LEAKING IN THE MIDDLE WHEN IT RAINS

CAUSE: CUSTOMER STATED THAT THE AWNING WAS LEAKING IN MIDDLE WHEN RAINING, DUE
TO SMALL GAP IN GUTTER

CORRECTION: SEALED GUTTER WITH SILICONE

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C

Subtotal for Job #2: 0.00

Job #3 - Internal

COMPLAINT: THERE IS A BLACK TRIM PIECE (NOT THE ELECTRICAL CORD) HANGING DOWN
FROM THE FRONT OF THE AWNING ROLLER TUBE. SEE BJ FOR DETAILS.

CAUSE: BLACK TRIM CAME OUT IN AWNING

CORRECTION: SLID TRIM BACK INTO PLACE

Labor



Customer #: 51342
KEYS, KEVIN D.



Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C

Subtotal for Job #3: 0.00

Job #4 - Internal

COMPLAINT: SHAWN BROKE LIGHT TRACK

CORRECTION: MOVED AWNING OUT A LITTLE, THEN REMOVED THE LED LIGHT STRIP AND TRACK. PUT LIGHT TRACK IN FIRST THEN THE LED LIGHT STRIP. TESTED LIGHT FUNCTIONS. WORKS AS SHOULD

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Parts

Part #	Description	Qty	Price	Total
6864	LED LIGHT TRACK ON	1.00	N/C	N/C
F100247635	LED LIGHTS FOR CAR	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-AWN LIGHT TRACK	1.00	N/C	N/C
FRT	FREIGHT 2ND SET OF LIGHTS	1.00	N/C	N/C

Subtotal for Job #4: 0.00

Parts Total:	137.91
Labour Total:	75.00
Sublet Total:	0.00
Extras Total:	15.93
WORK ORDER TOTAL:	228.84

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 13 May 2022

W/O: 67011
Promised Date: 30 APR 22



Customer #: 51342
KEYS, KEVIN D.

