

## Claim Response

Claim: C3056492

Last Modified by:stutk

| Claim    | Reference no. | Repair start date | Repair date | VIN               | Pre-auth | Dealer | Repairing dealer name                                             | Labor rate | Changed warranty rate | Type     | Date Of Purchase |
|----------|---------------|-------------------|-------------|-------------------|----------|--------|-------------------------------------------------------------------|------------|-----------------------|----------|------------------|
| C3056492 | 67031         | 4/8/2022          | 4/8/2022    | 4YDT20222M3110166 |          | 1194   | Basden's American RV<br>600 E Baseline Rd<br>Evansville, IN 47725 | 150.00     | 0.00                  | SA21-414 | 4/30/2021        |

| Deny code                                                   | Item number | Name                          | Quantity | Qty Returned | Dealer price | Markup | Part total | Appr Freight | Sub Freight | Sublet | Status   |
|-------------------------------------------------------------|-------------|-------------------------------|----------|--------------|--------------|--------|------------|--------------|-------------|--------|----------|
|                                                             | 692585      | Regulator - Kit - Auto Change | 1.00     | 0.00         | 48.79        | 15.00  | 56.11      | 0.00         | 0.00        | 0.00   | Approved |
| 5121839                                                     |             |                               |          |              |              |        |            |              |             |        |          |
| Component Model: 6020      Component Serial Number: N 20 46 |             |                               |          |              |              |        |            |              |             |        |          |
|                                                             | 446897      | Hose - LP - 12" Pigtail       | 2.00     | 0.00         | 6.65         | 15.00  | 15.30      | 0.00         | 0.00        | 0.00   | Approved |

5121839

| Deny code | Operation | Description                                                                                                                                                                                                                                                    | Srvc advisory | Sub hours | Apvd Hours | Labor amt | Sublet | Qty | Base Hours | Status   |
|-----------|-----------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|-----------|------------|-----------|--------|-----|------------|----------|
|           | 7141442B  | Safety Advisory 21-414 Winn-Tec<br>Complaint: KEYSTONE SAFETY ADVISORY LP<br>REGULATOR RECALL #21-414<br>SECTION:71 COMPONENT:414<br>OPERATION:7141442B<br>PART#380444<br>Cause: lp regulator recall<br>Correction: replaced with new lp regulator<br>(AP KBS) |               | 0.50      | 0.50       | 75.00     | 0.00   | 1   | 0.50       | Approved |

Submitted parts & subLet 71.41  
Submitted labor & subLet 75.00  
Submitted freight: 0.00  
Tax: 0.00  
Total Submitted: 146.41

Approved parts & subLet 71.41  
Approved labor & subLet 75.00  
Approved freight: 0.00  
Tax: 0.00  
Total approved: 146.41