

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b>	0005106	<b>CLAIM STATUS</b>	Authorized
BASDEN RV CENTER INC		<b>CLAIM</b>	1004023
DBA AMERICAN RV CENTER		<b>CLAIM ORIGIN</b>	WEB
600 E BASELINE ROAD		<b>ORIGINAL CLAIM ID</b>	
		<b>VIN</b>	4X4TCKH25NX157800
EVANSVILLE, IN 47725		<b>CHASSIS VIN</b>	
USA		<b>MILEAGE</b>	0
		<b>SITE/WAREHOUSE</b>	017 / 017A
<b>Labor rate:</b>	\$150.00	<b>ITEM #</b>	ACKT324TS
<b>OWNER INFORMATION</b>		<b>DEALER RO #</b>	67073
		<b>CLAIM START DATE</b>	04/14/2022
		<b>CLAIM END DATE</b>	01/01/1900

<b>Retail Date of Purchase</b>	<b>WARRANTY EXPIRATION DATE</b>
--------------------------------	---------------------------------

## Claim Line Details

**Labor**

<b>Line# 1</b>	<b>Operation Code</b> RC-003-05-00-004162	<b>Operational Description</b> 22V135, 2022-106 - PATRICK 50AMP SHORE INLETS - INSPECT ONLY - Recall/Electrical/Inspect/No Tread Code
	<b>Complaint, Cause, Correction</b>	
	Original Note : bhoffman@americanrvcenter.com, 2022-04-14 08:38:27 :: 22V135 THE LUGS ON THE SHORE CORD COULD BE LOOSE CHECK AND ADVISE check for recall pulled inlet, wires look good, lugs are tight. installed inlet and sealed with silicone	
	<b>Model #</b>	<b>Dlr Sub Hrs</b> 0.25
	<b>Serial #</b>	<b>Appr Hrs</b> 0.25
		<b>Sub Labor Amt</b> \$37.50
		<b>Appr Labor Amt</b> \$37.50
	<b>Notes</b>	

<b>Submitted</b>	Labor Amt	\$37.50	<b>Approved</b>	Labor Amt	\$37.50
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$37.50		Total	\$37.50

DEALER \_\_\_\_\_ DATE \_\_\_\_\_  
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER \_\_\_\_\_ DATE \_\_\_\_\_  
SIGNATURE

All repairs described have been inspected and are satisfactory.