

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1007003
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
		VIN	5ZT2CARB3NU039464
EVANSVILLE, IN 47725		CHASSIS VIN	
USA		MILEAGE	0
		SITE/WAREHOUSE	103 / 103
Labor rate:	\$150.00	ITEM #	CAT263BHCKLE
OWNER INFORMATION		DEALER RO #	67082
JUSTIN L BULLARD		CLAIM START DATE	04/16/2022
5 VICTORY LN		CLAIM END DATE	01/01/1900
Fairfield, IL 62837			
USA			
Retail Date of Purchase	02/12/2022	WARRANTY EXPIRATION DATE	02/12/2023

Claim Line Details

Labor

Line# 1	Operation Code 60-136-15-00-001499	Operational Description Water Line - Plumbing/Fresh Water Supply/Repair or Replace/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-04-16 10:04:18 :: CUSTOMER STATES THAT THERE IS A LEAK COMING FROM THE OUTDOOR SHOWER. THE WATER IS LEAKING AROUND THE SILICONE. hooked up water and pressurized system. pulled cover to access the back of the outside shower. fittings are leaking. tightened up fitting so they do not leak installed panel, removed hose, dried outdoor flange, sealed with silicone	
	Model #	Dlr Sub Hrs 0.60
	Serial #	Appr Hrs 0.60
		Sub Labor Amt \$90.00
		Appr Labor Amt \$90.00
	Notes AUTHORIZED AS REQUESTED	

Labor

Line# 2	Operation Code 30-100-01-00-001050	Operational Description Cabinet Stiles - Interior/Cabinetry/Replace/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-04-16 10:13:30 :: CUSTOMER ADVISED THAT THE WATER FROM THE OUTDOOR SHOWER HAS RAN INSIDE THE COACH AND CAUSED THE VANITY TO WARP. FOUND DAMAGED AREA THAT NEEDS TO BE REPLACED TAKE STYLE APART AND FIX	
	Model #	Dlr Sub Hrs 2.00
	Serial #	Appr Hrs 2.00
		Sub Labor Amt \$300.00
		Appr Labor Amt \$300.00
	Notes AUTHORIZED AS REQUESTED	

Labor

Line# 3	Operation Code 10-12-02-00-000217	Operational Description Slide Out Rollers - Frame & Chassis/Slide Out System - Lippert/Adjust/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-04-16 10:14:31 :: CUSTOMER SAYS THAT THE TOP OF THE SLIDE ROOM SUCKS IN TIGHTLY WHEN THE SLIDE ROOM IS CLOSED, BUT IT DIES NOT PULL IN TIGHTLY AT THE BOTTOM. pulled unit into shop. ran out slide to inspect brackets. brackets are even and marked from factory. bottom of slide is sealing but still sticks out a little further than the top. went over to look at the "bell" and i could turn it by hand. moved bell out so it would allow bottom of slide to pul in more. tightened lock nut so bell wouldn't move.	

Model #	Dir Sub Hrs	1.50	Sub Labor Amt	\$225.00
Serial #	Appr Hrs	1.00	Appr Labor Amt	\$150.00

Notes
EXCESSIVE AMOUNT REQUESTED

Submitted					Approved				
	Labor Amt	\$615.00				Labor Amt	\$540.00		
	Parts & Freight	\$0.00				Parts & Freight	\$0.00		
	Total	\$615.00				Total	\$540.00		

DEALER	DATE
SIGNATURE	
I certify that I have performed these repairs consistent with Forest River Policies.	

CUSTOMER	DATE
SIGNATURE	
All repairs described have been inspected and are satisfactory.	