



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 67082
Promised Date: 30 APR 22

CUSTOMER WORK ORDER

WO #: 67082 (Appointment Date: 12 APR 2022 - Time: 07:00am)

Customer: 52273 - BULLARD, JUSTIN L.
- 618-516-3017

Tag:

Author: BJW

Location: 0422 GET WITH BB TO GET
WORK COMPLETED

Stock #: 10646

Stock Desc: (10646) 2022 COACHMEN
CATALINA 263BHCKLE

Chassis #: 5ZT2CARB3NU039464

Serial #: 5ZT2CARB3NU039464

Mileage:

Licence:

Invoice #:

Date In: 12 APR 22

Promised: 30 APR 22

Date Sched:

Completed: 22 APR 22

Warr. Date: 12 FEB 22

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES THAT THERE IS A LEAK
COMING FROM THE OUTDOOR SHOWER. THE
WATER IS LEAKING AROUND THE
SILICONE.

CAUSE: hooked up water and
pressurized system. pulled cover to
access the back of the outside shower.
fittings are not leaking. water from
hose is dripping on the outside flange
of the outdoor shower. silicone has gaps
in it.

CORRECTION: installed panel, removed
hose, dried outdoor flange, sealed with
silicone

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	90.00

Subtotal for Job #1: 90.00

Job #2 - Warranty

COMPLAINT: CUSTOMER ADVISED THAT THE WATER FROM THE
OUTDOOR SHOWER HAS RAN INSIDE THE COACH
AND CAUSED THE VANITY TO WARP.

CORRECTION: REMOVED
CABINET DOOR. REMOVED FRONT CABINET
TRIM. BUILT NEW CABINET FRONT. CUT OFF
STAPLES. INSTALL NEW FRONT

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	300.00

Parts

Part #	Description	Qty	Price	Total
F100285185	STILE, LC 18MM" X	8.00	0.95	7.60

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-STILE	1.00	31.81	31.81



Customer #: 52273
BULLARD, JUSTIN L.



Subtotal for Job #2: 339.41

Job #3 - Warranty

COMPLAINT: CUSTOMER SAYS THAT THE TOP OF THE SLIDE ROOM SUCKS IN TIGHTLY WHEN THE SLIDE ROOM IS CLOSED, BUT IT DOES NOT PULL IN TIGHTLY AT THE BOTTOM.

CAUSE: pulled unit into shop. ran out slide to inspect brackets. brackets are even and marked from factory. bottom of slide is sealing but still sticks out a little further than the top. went over to look at the "bell" and i could turn it by hand.

CORRECTION: moved bell out so it would allow bottom of slide to pull in more. tightened lock nut so bell wouldn't move.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	150.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00

Subtotal for Job #3: 150.00

Parts Total: 7.60
Labour Total: 540.00
Sublet Total: 0.00
Extras Total: 31.81
WORK ORDER TOTAL: 579.41

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 22 Apr 2022

W/O: 67082
Promised Date: 30 APR 22



Customer #: 52273
BULLARD, JUSTIN L.

