



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

Estimate: 27491 MILLS, BILLY

Estimate: 27491 (Appointment Date: 05 AUG 2026 - Time: 09:00am)

Customer: 94190 - MILLS, BILLY
Address: W4207 TAGAY TAY TERRACE
WAUBEKA, WI
53021

Home Phone: (262) 685-2772

Work Phone:

Author: CLP

Location: IH

Invoice #:

Stock #:
Stock Desc: 2017 THFW PRIME TIME SPARTAN
Model:
Serial #: 5ZT3ST9F7HG301110
Chassis #:
Mileage:
Key #:
Req'n #:
License #:
Trim:

Purchase Date:
Date In: 23 JUL 26
Promise Date:
Promise Time:
Schedule Date:
Completed:
Warr. Date:

Job #1 - External

INSURANCE (EMAIL MADISON.CLM@AOINS.COM) PHONE 7155521462 X58703 CLAIM
#300-0423307-2026

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1	0.00	0.00
Subtotal for Job #1:				0.00

Job #2 - External

BED SLIDE IS STUCK AND WILL NOT COME IN CHECK AND ADVISE

Subtotal for Job #2: 0.00

Job #3 - External

ODS REAR SLIDE HAS WATER DAMAGE CHECK AND ADVISE

Subtotal for Job #3: 0.00

Job #4 - External

REAR STEPS ARE STUCK CHECK AND ADVISE

Subtotal for Job #4: 0.00

Job #5 - External

DS FLOOR FROM FRONT ENTRY DOOR TO TH BATH IS SOFT CHECK AND ADVISE

Subtotal for Job #5: 0.00

Job #6 - External

SCREENS ARE MISSING IN VENTS CHECK AND ADVISE



Subtotal for Job #6: 0.00

Job #7 - External

J WRAP ON ODS SLIDE IS LOOSE CHECK AND ADVISE

Subtotal for Job #7: 0.00

Job #8 - External

WHEN FLUSHING REAR BLACK TANK WATER ENTERED TH GARAGE CHECK AND ADVISE

Subtotal for Job #8: 0.00

Job #9 - External

STOVE GLASS HAS EXPLODED CHECK AND ADVISE

Subtotal for Job #9: 0.00

Job #10 - External

FUEL PUMP IS POPPING FUSES WHEN IN USE CHECK AND ADVISE

Subtotal for Job #10: 0.00

Job #ROOFINS - External

COMPLEMENTARY ROOF INSPECTION

CHECK CAULKING _____

CHECK SKYLIGHTS _____

CHECK ROOF VENTS _____

CHECK LUBE & ANTENNA _____

CHECK SATELLITE _____

CHECK RUBBER _____

Subtotal for Job #ROOFINS: 0.00

Job #11 - External

DS REAR SLIDE IS LEAKING CHECK AND ADVISE

Subtotal for Job #11: 0.00

Job #12 - External

BOTH AWNING FABRICS ARE TORN CHECK AND ADVISE

Subtotal for Job #12: 0.00

Job #13 - External

BEDS IN REAR ARE INOP CHECK AND ADVISE

Subtotal for Job #13: 0.00

Job #14 - External

QUOTE ON NEW FURNITURE



Subtotal for Job #14: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
Tax Total: 0.00
Estimate Total: 0.00

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 03 Aug 2026

Customer
Estimate

