



1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$669.65

RO# : 40568 Tag# : S11J0144

Check-in: Sat May 2, 2026 | 12:03 PM

Ready for Pickup: Fri Jun 26, 2026 | 1:35 PM

Promise Time: Thu May 7, 2026 | 6:00 PM

**Customer**  
linkautomotive - 2174  
PD7155200709I  
**Customer**  
1235491  
+1 - (715) 466 - 2222  
NO@GMAIL.COM  
1025 WI-77  
Minong, WI 54859

**Pickup-Customer**  
Same as Customer  
  
**Billing-Customer**  
Same as Customer

**Vehicle**  
2025 JAYCO  
BUNGALOW 40RLTS  
1UJBC0BV5S11J0144  
2 Mi In  
Sold Date: 04/30/2026  
Stock #: 25-22

**Service Advisor**  
CODY EAGLE  
codye

|    |               |                                           |              |          |
|----|---------------|-------------------------------------------|--------------|----------|
| A. | MISCELLANEOUS | DEALER STATES BED SLIDEOUT IS NOT OPENING | Warranty Pay | \$669.65 |
|----|---------------|-------------------------------------------|--------------|----------|

Job added by CODY EAGLE on Sat May 2, 2026 | 12:03 PM

1. Bad automatic circuit breaker/short

Op:1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$660.00

Labor Cost: \$96.00

| Technician | Certification Number | Actual Hours | Assigned Bill Hours | Flag Hours | Labor Sale | Labor Cost |
|------------|----------------------|--------------|---------------------|------------|------------|------------|
| boiem      | -                    | 0            | 0                   | 0          | \$0.00     | \$0.00     |
| matthewl   | -                    | 3.9          | 4                   | 4          | \$660.00   | \$96.00    |

1. slid dose not want to move when using switch, need to pull it in to the shop to see whats going on.

2. Switch did not respond. Removed switch, tested circuit for power, examined wiring, Checked fuses, checked motor, found blown automatic circuit breaker. Replaced automatic exterior circuit breaker. It was loose causing a short. Video also attached to RO (not in file, does not permit copy function for video). Found poor wiring connection to motor while testing motor. Respliced wires to motor. Found 20 amp auto reset fuse had loose connection to the interior circuit board. Receptive spade on board was too far spread causing a fault. Replaced fuse and crimped spade receptors to properly grip auto reset fuse. Tested unit for function. Put everything back together. Works as it should.

#### Parts

Parts Total Sale Amount \$9.65

Parts Total Cost Amount \$7.42

| Name                     | Quantity | Unit Price | Sale Price | Cost Price |
|--------------------------|----------|------------|------------|------------|
| 03074218 - 50AMP BREAKER | 1        | \$5.84     | \$5.84     | \$4.49     |
| 03071708 - FUSE          | 1        | \$3.81     | \$3.81     | \$2.93     |





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$669.65

RO# : 40568 Tag# : S11J0144

Check-in: Sat May 2, 2026 | 12:03 PM

Ready for Pickup: Fri Jun 26, 2026 | 1:35 PM

Promise Time: Thu May 7, 2026 | 6:00 PM

**Customer**

linkautomotive - 2174  
PD7155200709I  
Customer  
1235491  
+1 - (715) 466 - 2222

**Billing-Customer**

Same as Customer

**Vehicle**

2025 JAYCO  
BUNGALOW 40RLTS  
1UJBC0BV5S11J0144

**Service Advisor**

CODY EAGLE  
codye

Total Labor Sale  
\$660.00

Total Labor Cost  
\$96.00

Total Parts Sale  
\$9.65

Total Parts Cost  
\$7.42

|    |               |                                                       |              |        |
|----|---------------|-------------------------------------------------------|--------------|--------|
| B. | MISCELLANEOUS | DEALER STATES HOLE BEHIND COUCH NEEDS TO BE FILLED IN | Warranty Pay | \$0.00 |
|----|---------------|-------------------------------------------------------|--------------|--------|

Tags:

Add-on

Job added by BECKY DALEIDEN on Mon May 4, 2026 | 9:18 AM

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$0.00

| Technician | Certification Number | Actual Hours | Assigned Bill Hours | Flag Hours | Labor Sale | Labor Cost |
|------------|----------------------|--------------|---------------------|------------|------------|------------|
| boiem      | -                    | 0            | 0                   | 0          | \$0.00     | \$0.00     |

Total Labor Sale  
\$0.00

Total Labor Cost  
\$0.00

Total Parts Sale  
\$0.00

Total Parts Cost  
\$0.00

| Additional Fees           | Sale Amount | Cost Amount |
|---------------------------|-------------|-------------|
| SSC - Shop Supply Charges | \$0.00      | \$0.00      |





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
**\$669.65**

**RO# : 40568 Tag# : S11J0144**

Check-in: Sat May 2, 2026 | 12:03 PM

Ready for Pickup: Fri Jun 26, 2026 | 1:35 PM

Promise Time: Thu May 7, 2026 | 6:00 PM

**Customer**  
linkautomotive - 2174  
PD7155200709I  
Customer  
1235491  
+1 - (715) 466 - 2222

**Billing-Customer**  
Same as Customer

**Vehicle**  
2025 JAYCO  
BUNGALOW 40RLTS  
1UJBC0BV5S11J0144

**Service Advisor**  
CODY EAGLE  
codye

|  | Category             | Sale            | Cost            |
|--|----------------------|-----------------|-----------------|
|  | Labor                | \$660.00        | \$96.00         |
|  | Parts                | \$9.65          | \$7.42          |
|  | Sublet               | \$0.00          | \$0.00          |
|  | Sublet Labor         | \$0.00          | \$0.00          |
|  | Sublet Parts         | \$0.00          | \$0.00          |
|  | Fees                 | \$0.00          | \$0.00          |
|  | Discounts            | \$0.00          | -               |
|  | Tax                  | \$0.00          | -               |
|  | Deductible           | \$0.00          | -               |
|  | Insurance/Warranty   | \$0.00          | -               |
|  | <b>Invoice Total</b> | <b>\$669.65</b> | <b>\$103.42</b> |

### Clock In Info

| #                 | Opcode | Date            | Clock In  | Clock Out | Time Spent | Pay Type | Technician | Flag Hrs |
|-------------------|--------|-----------------|-----------|-----------|------------|----------|------------|----------|
| A                 | MISC   | Mon May 4, 2026 | 9:17 AM   | 10:36 AM  | 1.32 hrs   | W        | matthewl   | 4 hrs    |
| Tag: Regular Hour |        |                 | Reason: - |           |            |          |            |          |
| A                 | MISC   | Tue May 5, 2026 | 11:04 AM  | 11:33 AM  | 0.48 hrs   | W        | matthewl   | -        |
| Tag: Regular Hour |        |                 | Reason: - |           |            |          |            |          |
| A                 | MISC   | Tue May 5, 2026 | 12:53 PM  | 2:59 PM   | 2.10 hrs   | W        | matthewl   | -        |
| Tag: Regular Hour |        |                 | Reason: - |           |            |          |            |          |
| A                 | MISC   | -               | -         | -         | 0 hrs      | W        | boiem      | 0 hrs    |
| B                 | MISC   | -               | -         | -         | 0 hrs      | W        | boiem      | 0 hrs    |





1025 WI-77 Minong WI US 54859 www.linkrvidirect.com

Invoice  
**\$669.65**

**RO# : 40568 Tag# : S11J0144**

Check-in: Sat May 2, 2026 | 12:03 PM

Ready for Pickup: Fri Jun 26, 2026 | 1:35 PM

Promise Time: Thu May 7, 2026 | 6:00 PM

**Customer**

linkautomotive - 2174  
PD7155200709I  
Customer  
1235491  
+1 - (715) 466 - 2222

**Billing-Customer**

Same as Customer

**Vehicle**

2025 JAYCO  
BUNGALOW 40RLTS  
1UJBC0BV5S11J0144

**Service Advisor**

CODY EAGLE  
codye

**Accounting Info - Warranty**

| GL Account # | Control # | Franchise | Amount    |
|--------------|-----------|-----------|-----------|
| 11400        | 40568     | LINK RV   | \$669.65  |
| 57200        | 40568     | LINK RV   | -\$660.00 |
| 67200        | 40568     | LINK RV   | \$96.00   |
| 14400        | boiem     | LINK RV   | \$0.00    |
| 14400        | matthewl  | LINK RV   | -\$96.00  |
| 54200        | 40568     | LINK RV   | -\$9.65   |
| 64000        | 40568     | LINK RV   | \$7.42    |
| 14000        | 40568     | LINK RV   | -\$7.42   |

