

Claim Response

Claim: C3071230

Non-Warranty Goodwill Adjustment

Last Modified by ambri

Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed warranty rate	Type	Date Of Purchase
C3071230	67137	4/25/2022	4/25/2022	4YDT20224L3104772		1194	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	150.00	0.00	SA21-414	5/8/2020

Deny code	Item number	Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
	692585	Regulator - Kit - Auto Change	1.00	0.00	48.79	15.00	56.11	0.00	0.00	0.00	Approved
5121839											
Component Model: 6020			Component Serial Number: N 19 04								
	446897	Hose - LP - 12" Pigtail	2.00	0.00	6.65	15.00	15.30	0.00	0.00	0.00	Approved

5121839

39	446897	Hose - LP - 12" Pigtail	2.00	0.00	6.65	15.00	15.30	0.00	0.00	0.00	Denied
----	--------	-------------------------	------	------	------	-------	-------	------	------	------	--------

Parts claimed not supported by repair detail
only 2 pigtails per regulator

Deny code	Operation	Description	Srvc advisory	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	7141442B	Safety Advisory 21-414 Winn-Tec Complaint: REGULATOR RECALL Cause: PART OF RECALL Correction: CHANGED REGULATOR FOR RECALL. CHECKED FOR LEAKS AND PRESSURE. (AP KBS)		0.50	0.50	75.00	0.00	1	0.50	Approved

Submitted parts & subLet 86.71
Submitted labor & subLet 75.00
Submitted freight: 0.00
Tax: 0.00
Total Submitted: 161.71

Approved parts & subLet 71.41
Approved labor & subLet 75.00
Approved freight: 0.00
Tax: 0.00
Total approved: 146.41