

Claim Response

Claim: C3066870

Last Modified byGrimS

Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed warranty rate	Type	Date Of Purchase
C3066870	67150	4/19/2022	4/20/2022	4YDT25123M3111857		1194	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	150.00	0.00	SA21-414	5/27/2021

Deny code	Item number	Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
	692585	Regulator - Kit - Auto Change	1.00	0.00	48.79	15.00	56.11	0.00	0.00	0.00	Approved
5121839 5121839											
Component Model: 6020		Component Serial Number: N 19 50									
	446897	Hose - LP - 12" Pigtail	2.00	0.00	6.65	15.00	15.30	0.00	0.00	0.00	Approved

Deny code	Operation	Description	Srvc advisory	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
7141442B	Safety Advisory	21-414 Winn-Tec Complaint: RECALL ON LP REGULATOR Cause: RECALL ON LP REGULATOR. Correction: Moved unit into shop from service lot. Checked LP regulator against recall list. Lp regulator is on list and needs replaced. Removed old LP regulator from unit. Disconnected hose fromchassis to regulator. Assembled pigtail LP hoses and mounting bracket to new regulator. Connected new regulator to chassis holse. Installed and connected to lp tanks. Performed LP drop test and set lp pressure at 11.0 in.wc. with furnace and water heater operating. Checked all connections for leaks. N 19 50 6020		0.50	0.50	75.00	0.00	1	0.50	Approved

Submitted parts & subLet	71.41	Approved parts & subLet	71.41
Submitted labor & subLet:	75.00	Approved labor & subLet	75.00
Submitted freight:	0.00	Approved freight:	0.00
Tax:	0.00	Tax:	0.00
Total Submitted:	<u>146.41</u>	Total approved:	<u>146.41</u>