



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 67160

## CUSTOMER WORK ORDER

WO #: 67160

Customer: 1000 - BASDEN'S AMERICAN  
RV -  
Tag:  
Author: BH  
Location: 0503 CHECK PREAUTH

Stock #: 11217  
Stock Desc: 2022 TT RIVERSIDE RV  
RETRO 165  
Chassis #: 59CCC4812NL005729  
Serial #: 59CCC4812NL005729  
Mileage: 0  
Licence:

Invoice #:  
Date In: 21 APR 22  
Promised:  
Date Sched:  
Completed: 30 APR 22  
Warr. Date:

### Job #BUNKHOUSE - Internal

COMPLAINT: Transferred to BAS\*67293 on 30 APR 22  
Estimate amount was 0.00  
PRE DELIVERY INSPECTION NEW BUNKHOUSE

CORRECTION: PREFORMED PDI ON NEW UNIT

#### Labor

| Code | Description                 | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | RAB      | N/C   |
| Z990 | MISC LABOUR CODE (EXTERNAL) | RAB      | N/C   |
| Z990 | MISC LABOUR CODE (EXTERNAL) | RAB      | N/C   |
| Z990 | MISC LABOUR CODE (EXTERNAL) | RAB      | N/C   |
| Z990 | MISC LABOUR CODE (EXTERNAL) | RAB      | N/C   |

#### Other Services

| Code | Description   | Qty  | Price | Total |
|------|---------------|------|-------|-------|
| LPG  | LP GAS        | 0.00 | N/C   | N/C   |
| SS   | SHOP SUPPLIES | 0.00 | N/C   | N/C   |

**Subtotal for Job #BUNKHOUSE: 0.00**

### Job #1 - Warranty

COMPLAINT: FRIDGE DOOR HANDLE WILL NOT OPEN AND IS CRACKED

CAUSE: FRIDGE DOOR HANDLE WOULDNT OPEN. IT WAS STUCK DUE TO CRACKED AND BINDED HANDLE

CORRECTION: REPLACED AND INSTALLED NEW REFER HANDLE

#### Labor

| Code | Description                 | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | RAB      | 30.00 |
| Z990 | MISC LABOUR CODE (EXTERNAL) | RAB      | 0.00  |

#### Parts

| Part # | Description        | Qty  | Price | Total |
|--------|--------------------|------|-------|-------|
| 080611 | S,STD DR HANDLE CO | 1.00 | 37.39 | 37.39 |

**Subtotal for Job #1: 67.39**

### Job #2 - Warranty

COMPLAINT: SCREEN DOOR WILL NOT LATCH

CAUSE: SCREEN DOOR WOULD NOT LATCH DUE TO NIT BEING SCREWED IN RIGHT



Customer #: 1000  
BASDEN'S AMERICAN RV,



CORRECTION: TIGHTENED UP SCREWS AND ADJUSTED LATCH

| <b>Labor</b>                |                             |          |              |
|-----------------------------|-----------------------------|----------|--------------|
| Code                        | Description                 | Mechanic | Total        |
| Z990                        | MISC LABOUR CODE (EXTERNAL) | RAB      | 15.00        |
| <b>Subtotal for Job #2:</b> |                             |          | <b>15.00</b> |

**Job #3 - Warranty**

COMPLAINT: MAIN DOOR BOWED OUT AT THE BOTTOM

CAUSE: MIN DOOR BOWED DUE TO STRIKEPLATE BEING BENT CAUSIND DOOR NOT TO LATCH PROPERLY ALONG WITH DOOR STRUT BEING LOSE

CORRECTION: BENT STRIKE PLATE BACK,TIGHTEN DOWN THE SCREWS AND TIGHTEN DOWN THE DOOR STRUT

| <b>Labor</b>                |                             |          |              |
|-----------------------------|-----------------------------|----------|--------------|
| Code                        | Description                 | Mechanic | Total        |
| Z990                        | MISC LABOUR CODE (EXTERNAL) | RAB      | 60.00        |
| <b>Subtotal for Job #3:</b> |                             |          | <b>60.00</b> |

**Job #4 - Warranty**

COMPLAINT: THE SHOWER HEAD IS BUSTED.

CAUSE: SHOWER HEAD WAS LEAKING DUE TO CRACK/BUSTED CONNECTION

CORRECTION: REPLACED WITH NEW SHOWER HEAD

| Labor                |                             |      |          |       |
|----------------------|-----------------------------|------|----------|-------|
| Code                 | Description                 |      | Mechanic | Total |
| Z990                 | MISC LABOUR CODE (EXTERNAL) |      | RAB      | 30.00 |
| Parts                |                             |      |          |       |
| Part #               | Description                 | Qty  | Price    | Total |
| DF-SA130-WT          | WHITE HEAD AND HOS          | 1.00 | 20.14    | 20.14 |
| Subtotal for Job #4: |                             |      |          | 50.14 |

|                          |               |
|--------------------------|---------------|
| Parts Total:             | 57.53         |
| Labour Total:            | 135.00        |
| Sublet Total:            | 0.00          |
| Extras Total:            | 0.00          |
| <b>WORK ORDER TOTAL:</b> | <b>192.53</b> |

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 03 May 2022

Customer #: 1000  
BASDEN'S AMERICAN RV,