

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13754

Date In: 03 JUL 26 Author: DLUCAS
Promised Date: 10 JUL 26 Stock No: 11093
: Year: 2023
Customer Name: 14593 - VANDER MOLEN, Manufacturer: FOREST RIVER
Address: 4416 S 80TH ST Brand: PUMA TT
: GREENFIELD, WI Model: 32BHFS
Postal/Zip: 53220 Miles/Hrs: 0
Phone#(res): 4142026525 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: MJVANDERMOLEN@GMAIL.CO Tag#:
Purchased Date: 08 JUL 24 :
Delivery Date: 22 JUL 24 :
InService Date: :
Serial#: 4X4TPUH21PP098036 :

Job # Description JOB INFORMATION Type Bill To

SC CUSTOMER REQUESTS SERVICE CALL TO 1005 LONGBOW COURT E 14593 VANDE
1 COMPLAINT: CUSTOMER STATES THERE IS SIGNIFICANT E 14593 VANDE
DAMAGE FROM WATER INTRUSION INTO
SLIDEOUT IN SPOTS, ONLY RUBBER NO WOOD
WOULD LIKE DIAGNOSIS / ESTIMATE ON
REPAIRS
CAUSE: pics and measurements taken on door side
slide what I found was on exterior roof
leaking on that slide where the rubber
meets the fascia wood on interior the the
metal trim piece that go across the
slide to hold rubber down the screws
pulled out allowing water in and
leaking down the interior fascia wood
and batten strip causing to swell and
Crack will need a new a new slide rubber
and slide decking also on inside of
slide out will need 1 upper fascia board
and 1 side fascia board 2 side trim
boards that go around refrigerator 3 ich
wide at least 70 inches long also two
full batten strips and on lower of
refrigerator will need 1 - 2 ich wide
1/2 thick goes for all trim work around
refrigerator thickness possible 1 wall
paneling board and 1 ceiling panel
**CUSTOMER WOULD LIKE NOTED THAT WATER
INTRUSION WAS GETTING INTO REFER**

Continued on page 2

Work Order : 13754

 Job # Description JOB INFORMATION Type Bill To

 CORRECTION: estimate
 EST ESTIMATE SLIDE REPAIR W 1021 FORES

 Job # Part No Description PARTS Bill to Qty Price Total

 EST EST CEILING PANEL W-1021 0 32.50 0.00
 EST EST WALL PANEL W-1021 0 32.50 0.00
 EST EST BATTEN STRIP W-1021 0 32.50 0.00
 EST EST BATTEN STRIP W-1021 0 32.50 0.00
 EST EST TRIM BOARDS W-1021 0 32.50 0.00
 EST EST SIDE FASCIA W-1021 0 32.50 0.00
 EST EST UPPER FASCIA W-1021 0 32.50 0.00
 EST 677917010431 DIFLEX II SLIDEOUT ROOF W-1021 0 109.75 0.00

 Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total

 1 DIAG DIAGNOSTICS JS E-14593 1.00 130.00 130.00
 EST RV30I-8 ROOF R&R RUBBER (PER L W-1021 0.00 140.00 0.00
 EST RV32E-5 CEILING PANEL R&R (PER W-1021 0.00 140.00 0.00
 EST RV32E-6 WALL/CABINET PANEL R&R W-1021 0.00 140.00 0.00
 EST TMOLD T MOLDING R & R ON SLI W-1021 0.00 140.00 0.00
 EST TMOLD T MOLDING R & R ON SLI W-1021 0.00 140.00 0.00
 EST RV31I-3 DECK R&R (PER SHEET) R W-1021 0.00 140.00 0.00
 EST RV30G-3 MOLDING R&R FLAT/CORNE W-1021 0.00 140.00 0.00
 EST RV32E-1 BATTEN MOLDING R&R/NEW W-1021 0.00 140.00 0.00

 Job # Excode Description EXTRAS bill to Qty Price Total

 SC SSE SHOP SUPPLIES - EXTERNAL E-14593 1.00 9.75 9.75
 SC SC SERVICE CALL E-14593 15.00 3.75 56.25

 BILLINGS SUMMARY
 Type Bill Id Parts Labour Sublet Extras Tax Total

 E 14593 0.00 130.00 0.00 66.00 10.80 206.80
 Totals 0.00 130.00 0.00 66.00 10.80 206.80

&k2S
 &k0S