



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

Estimate: 27492 COOPER, MICHAEL



Estimate: 27492 (Appointment Date: 24 JUL 2026 - Time: 09:00am)

Customer: 90650 - COOPER, MICHAEL
Address: 19090 ESSEX DR
ABINGDON, VA
24211

Home Phone: 276-739-0003

Work Phone:

Author: CLP

Location: IH

Invoice #:

Stock #: 10812

Stock Desc: (10812) 2020 FOREST RIVER

ROCKWOOD GEO 19QB

Model: 19QB

Serial #: 5ZT2RSHC8L3008082

Chassis #:

Mileage:

Key #:

Req'n #: 62917

License #:

Trim:

Purchase Date: 08 SEP 23

Date In: 24 JUL 26

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date: 08 SEP 23

Job #1 - External

COMPLAINT: CUSTOMER TOW LIGHTS AND BRAKES ARE INOP CHECK AND ADVISE BOTH ISSUES ARE ONLY ON THE RIGHT SIDE. CUST STATED HE HAS DONE CHANGED THE LIGHT AND ISSUE STILL HAPPENING. THE LEFT WORKING AS IT SHOULD.

CORRECTION: CHECKED ALL LIGHTS AND THEY ARE WORKING AS SHOULD. JACKED UP EACH SIDE AND CHECKED BRAKES, THEY ARE WORKING PROPERLY.

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1	0.00	0.00
Subtotal for Job #1:				0.00

Job #2 - External

CUST HAS EXT WARRANTY

Subtotal for Job #2: 0.00

Job #ROOFINS - External

COMPLAINT: COMPLEMENTARY ROOF INSPECTION

CHECK CAULKING_____

CHECK SKYLIGHTS_____

CHECK ROOF VENTS_____

CHECK LUBE & ANTENNA_____

CHECK SATELLITE_____

CHECK RUBBER_____

CORRECTION: SCRAPED AND SEALED

Labor

Code	Description	Hours	Rate	Total
Z990	BERING PACK	0	175.00	0.00

Parts

Part #	Description	Qty	Price	Total
38-9018	LAP SEALANT WHITE	0	13.49	0.00

Subtotal for Job #ROOFINS: 0.00

Job #4 - External

COMPLAINT: CUST WOULD LIKE A BEARING REPACK DONE



CORRECTION: BEARINGS REPACKED

Labor

Code	Description	Hours	Rate	Total
Z990	BEARING PACK	0	175.00	0.00

Parts

Part #	Description	Qty	Price	Total
6520900	GREASE SEAL	0	12.59	0.00

Subtotal for Job #4: 0.00

Job #5 - External

CUST CAN NOT GET THE WIFI IN THE UNIT TO WORK THIS HAS BEEN A ISSUE SINCE HE PURCHASED THE UNIT

Parts

Part #	Description	Qty	Price	Total
19-1861	MULTI PURP ROCKER SWITCH	0	4.49	0.00

Subtotal for Job #5: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
Tax Total: 0.00
Estimate Total: 0.00

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 05 Aug 2026

