

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106
BASDEN RV CENTER INC
DBA AMERICAN RV CENTER
600 E BASELINE ROAD
EVANSVILLE, IN 47725
USA

Labor rate: \$150.00
OWNER INFORMATION

CLAIM STATUS Authorized
CLAIM 1026207
CLAIM ORIGIN WEB
ORIGINAL CLAIM ID
VIN 4X4TCKC25NX158985
CHASSIS VIN
MILEAGE 0
SITE/WAREHOUSE 017 / 017A
ITEM # ACKT274BRB
DEALER RO # 67229
CLAIM START DATE 05/02/2022
CLAIM END DATE 01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor
Line# 1 **Operation Code** **Operational Description**
30-101-24-00-001076 Hinged Passage Door - Interior/Interior Doors/Repair/No Tread Code
Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2022-05-02 13:15:35 :: BEDROOM DOOR HAS SCRATCHES SOME SMALL SCRATCHES ON DOOR COVERED THEM WITH WOOD PUTTY
Model # **Dlr Sub Hrs** 0.20 **Sub Labor Amt** \$30.00
Serial # **Appr Hrs** 0.20 **Appr Labor Amt** \$30.00

Notes

Labor
Line# 2 **Operation Code** **Operational Description**
20-46-19-00-000721 Window - Exterior/Windows/Reseal/No Tread Code
Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2022-05-02 13:17:14 :: SEALER ON METAL DOORS AND WINDOWS SEALER OM METAL DOORS AND WINDOW AND HANDLES FROM FACTORY REVIVED SELANT OFF DOORS WINDOWS AND HANDLES
Model # **Dlr Sub Hrs** 0.20 **Sub Labor Amt** \$30.00
Serial # **Appr Hrs** 0.20 **Appr Labor Amt** \$30.00

Notes

authorized as requested

Labor
Line# 3 **Operation Code** **Operational Description**
20-58-24-00-000813 Lower Radius Metal - Exterior/Metal, Aluminum Siding/Repair/No Tread Code
Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2022-05-02 13:18:33 :: J-RAP ON DOOR SIDE LOOSE J-RAP ON DOOR SIDE WAS LOSE DUE TO SCREWS NOT BEING TIGHT AND ONE SCREW BEING THE WRONG SIZE TIGHTEN SCREWS AND INSTALLED CORRECT SCREW
Model # **Dlr Sub Hrs** 0.10 **Sub Labor Amt** \$15.00
Serial # **Appr Hrs** 0.10 **Appr Labor Amt** \$15.00

Notes

authorized as requested

Labor
Line# 4 **Operation Code** **Operational Description**
20-66-24-00-000658 Entry Door - Exterior/Entry Doors/Repair/No Tread Code
Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2022-05-02 13:27:37 :: MAIN DOOR HARD TO CLOSE

MAIN DOOR WAS HARD TO CLOSE AND LATCH DUE TO STRIKING PLATE BEING ON WRONG INSTALLED STRIKING PLATE PROPERLY

Model #	Dir Sub Hrs	0.30	Sub Labor Amt	\$45.00
Serial #	Appr Hrs	0.30	Appr Labor Amt	\$45.00

Notes

authorized as requested

**Labor
Line# 5**

Operation Code	Operational Description
30-307-24-11-001183	Fireplace - Interior/Fireplace/Repair/Electrical

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2022-05-02 13:29:00 :: FIREPLACE NOT WORKING FIRE PLACE WOULD NOT TURN ON AT REMOTE OT AT THE CONTROL PANEL ON FIRE PLACE, DUE TO NOT BEING PLUGGED IN PROPERLY AT THE FACTORY PLUGGED IN PROPERLY AND REINSTALLED MOUNTING SCREWS

Model #	NA	Dir Sub Hrs	0.50	Sub Labor Amt	\$75.00
Serial #	NA	Appr Hrs	0.50	Appr Labor Amt	\$75.00

Notes

authorized as requested

**Labor
Line# 6**

Operation Code	Operational Description
40-106-01-12-001221	Tail Light Assembly - Surface Mount, each - Electrical/12 Volt Exterior/ Replace/Exterior Lighting

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2022-05-02 13:30:43 :: LEFT MARKER LIGHT MISSING LENS` left marker light lens missing replaced with new lens

Model #		Dir Sub Hrs	0.30	Sub Labor Amt	\$45.00
Serial #		Appr Hrs	0.20	Appr Labor Amt	\$30.00

Notes

lens only

Submitted

Labor Amt	\$240.00
Parts & Freight	\$0.00
Total	\$240.00

Approved

Labor Amt	\$225.00
Parts & Freight	\$0.00
Total	\$225.00

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.