



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 6729

CUSTOMER WORK ORDER

WO #: 67229

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: P.HUNT
Location: 0509 BEN CLOSE

Stock #: 10916
Stock Desc: 2022 TT FOREST RIVER
CHEROKEE 274BRB
Chassis #: 4X4TCKC25NX158985
Serial #: 4X4TCKC25NX158985
Mileage: 0
Licence:

Invoice #:
Date In: 25 APR 22
Promised:
Date Sched:
Completed: 30 APR 22
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CORRECTION: PDI NEW TRAVEL TRAILER

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C

Parts

Part #	Description	Qty	Price	Total
13-1287	NON SELF LEVELING	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #2 - Warranty

COMPLAINT: BEDROOM DOOR HAS SCRATCHES

CAUSE: SOME SMALL SCRATCHES ON DOOR

CORRECTION: COVERED THEM WITH WOOD PUTTY

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	30.00

Subtotal for Job #2: 30.00

Job #3 - Warranty

COMPLAINT: SEALER ON METAL DOORS AND WINDOWS

Customer #: 1000
BASDEN'S AMERICAN RV,



CAUSE: SEALER OM METAL DOORS AND WINDOW AND HANDLES FROM FACTORY

CORRECTION: REVIVED SELANT OFF DOORS WINDOWS AND HANDLES

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	6.00
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	24.00

Subtotal for Job #3: 30.00

Job #4 - Warranty

COMPLAINT: J-WRAP ON DOOR SIDE LOOSE

CAUSE: J-WRAP ON DOOR SIDE WAS LOSE DUE TO SCREWS NOT BEING TIGHT AND ONE SCREW BEING THE WRONG SIZE

CORRECTION: TIGHTEN SCREWS AND INSTALLED CORRECT SCREW

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	15.00

Subtotal for Job #4: 15.00

Job #1 - Warranty

COMPLAINT: MAIN DOOR HARD TO CLOSE

CAUSE: MAIN DOOR WAS HARD TO CLOSE AND LATCH DUE TO STRIKING PLATE BEING ON WRONG

CORRECTION: INSTALLED STRIKING PLATE PROPERLY

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	45.00

Subtotal for Job #1: 45.00

Job #5 - Warranty

COMPLAINT: FIREPLACE NOT WORKING

CAUSE: FIRE PLACE WOULD NOT TURN ON AT REMOTE OT AT THE CONTROL PANEL ON FIRE PLACE, DUE TO NOT BEING PLUGGED IN PROPERLY ATH THE FACTORY

CORRECTION: PLUGGED IN PROPERLY AND REINSTALLED MOUNTING SCREWS

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	75.00

Subtotal for Job #5: 75.00

Job #6 - Warranty

COMPLAINT: LEFT MARKER LIGHT MISSING LENS`

CAUSE: left marker light lens missing

CORRECTION: replaced with new lens

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	30.00

W/O: 6-7229



Customer #: 1000
BASDEN'S AMERICAN RV,



Parts

Part #	Description	Qty	Price	Total
523675	523675 RED ELLIPTI	1.00	2.63	2.63
Subtotal for VOB #0:				32.63

W/O: 6719

Parts Total: 2.63
Labour Total: 225.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 227.63

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 09 May 2022



Customer #: 1000
BASDEN'S AMERICAN RV,

