

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 67232
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725

Phone:

Stock Number: 11086 - 2022 SABRE 37FLL 5TZ3SR2B2N6111193
VIN: 5TZ3SR2B2N6111193 HIN: SER#: 5TZ3SR2B2N6111193
Mileage: 0 Work Order Comp: 31 MAY 22
Auth. No: Dealer #:
Warr. Date: Work Order Date: 25 APR 22 Inv #: 377733

WO # Job # Description JOB INFORMATION

67232 4 SLIDE SKI ON THE FLOOR ON THE FRIDGE SLIDE SIDE IS TORN AND NEEDS
TO BE REPLACED
FIND UNIT ON SLAES LOT AND CLOSE UP, BRING IN, OPEN SLIDEROOM,
GET JACK AND CUT BOARD TO USE TO LIFT SLIDEROOM OFF OF SLIDE
PLATE, FOUND 2 SCREWS STIKING UP ABOVE SLIDE PLATE, JACK ROOM UP
AND GOT 3/4 IN SPACE BETWEEN SCEW HEAD AND SLIDEROOM FLOOR, GET A
#2 BIT AND CUT DOWN TOO FIT TOOL TO 3/4 IN, USE 90 DEG PIC TO GET
PLASTIC AND WOOD OUT OF SCREW HEADS, WORK TOOL UNDER SLIDEROOM
FLOOR AND IN TO SCREW HEADS, USE FLAT SCREW DRIVER TOO HOLD BIT
IN SCREW HEADS AND SCREW IN BY HAND 1/4 OF TURN AT A TIME GET
BOTH SCREWS BELOW TOP OF SLIDE PLATE, INSTALL NEW SLIDE SKI ,
TEST ROOM AND CLOSE UP AND PULL BACK TO SLES LOT AND OPEN UP

67232 1 OUTSIDE REFRIDGERATOR DOOR HITTING SCREWS
mounting screw is hitting the bottom of the door.
removed screw under door. got a flat head screw and installed.
door was still hitting. added a shim at the bottom door hinge.
door clears screw.

67232 3 BED ROOM WALL BOARD LOOSE AT SEAM BELOW WINDOW OFF DOOR SIDE
PANEL CAME LOOSE. NEED TO SECURE TO WALL.
SECURED PANEL WITH BRAD NAILS AND FILLED HOLES WITH PUTTY.

67232 5 INSIDE SPEAKER NOT WORKING
REMOVED RADIO AND FOUND THE WIRE CONNECTOR CAME LOOSE
SECURED WIRES AND INSTALLED RADIO.

Claim : 67232

 WO # Job # Description JOB INFORMATION

67232 6 ENTRANCE DOOR BOWED AT TOP AND BOTTOM
 top and bottom of door are bowed in towards the door frame.
 took 2 pieces of wood and taped to the inside of the door where
 it was bowed in. shut the door and pushed around top and bottom
 the pull the door away from the frame.

Part No	Job#	Description	PARTS	Qty	Price	Total
20X38656A	4	TRIM, SKI 2.5" x 4		1.00	3.68	3.68
20X38655A	4	TRIM, SKI 2.5" x 4		1.00	5.43	5.43

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.00	150.00	0.00
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.50	150.00	75.00
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.10	150.00	15.00
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.20	150.00	30.00
Z990	5	MISC LABOUR CODE (EXTERNAL)		0.30	150.00	45.00
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.30	150.00	45.00

Excode	Job#	Description	EXTRAS	Qty	Price	Total
FRT	4	UPS-SKIS		1.00	15.99	15.99

Parts Total: 9.11
 Labour Total: 210.00
 Sublet Total: 0.00
 Extras Total: 15.99

>>>> Claim Total: 235.10

Customer Signature: _____

Date: _____