



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73722
Promised Date:
47 1111 26



WO #: 73722 (Appointment Date: 15 JUL 2026 - Time: 08:15am)
Customer Name: 61799 - BELTRAN, MONICA
Completed Date: 21 JUL 26
Invoice#:
Author: BRIAN
Stock Desc: 9557 2026 AVENGER 22MK
Serial#: 5ZT2AVLB4TB940664
Chassis#: 5ZT2AVLB4TB940664
Miles/Hrs:
Tag#: 7286
Purchased Date: 19 JUN 26
Warranty Date: 19 JUN 26
Date In: 15 JUL 26
Time In:

Job #0 - Warranty

CLAIM: 2747783

Subtotal for Job #0: 0.00

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES WATER LEAK AND KINKED LINE IN BATHROOM UNDER SINK

CAUSE: Kinked line and water leak on a tee

CORRECTION: Connect the unit to city water pressurized the unit went to each of the faucets make sure air was out of the line so it was at full pressure for water
Open the cabinet door underneath the bathroom sink began checking the waterlines where they connect to the actual faucet at the bottom of the faucet no leaks found
Began checking the rest of the waterlines behind the shelf. Some of the lines had enough slack to pull up and examine did see one of the cold water lines that was kinked.
Remove the access panel at the base of the bathroom vanity cabinet, and looked underneath where the water pump is could see that there was enough slack and waterlines to be able to lift the waterlines upwards to be able to check the rest of the connections did find one T in the cold water line that was dripping from a crimp ring. Did you get necessary tools, cutters crimpers a new tea? New crimper rings was able to cut one of the crimp rings underneath the sink disconnect the cold waterline from the base of the bathroom faucet. Bring the rest of the line outward part of the tea was for the city water connection cut the other two crimp rings off remove the existing T trimmed the waterlines off where they had already been cramped installed the new T crimping the all the lines back in place prior to crimping it back into full place I was able to rotate the one crimp line to where it was no longer cramped, but it was now a Loop reconnected the waterline to the base of the faucet turned on the city water supply again again emptying all the lines to ensure all air was out of the lines ran water through the bathroom faucet turned the water off at the faucet, allowed it to sit under pressure, checked all water connections from the water pump all the way to the bathroom faucet underneath did not detect any new leaks. The crimp in the one waterline was now taken care of this job is now complete. I did reinstall the base access panel with the four screws that it was attached with originally.

Requesting 1.5 hours labor due

Labor

Job #	Description	Total
1	WATER SYSTEM TROUBLESHOOT	285.00

Parts

Part #	Description	Qty	Price	Total
88-9165	1/2 PLUMB-PEX CLAMP (OETIKER)	3.00	0.63	1.89
15173	BRASS T 1/2" X 1/2" X 1/2"	1.00	3.77	3.77

Customer #: 61799
BELTRAN, MONICA



W/O: 73722
Promised Date: 17 JUL 26



Customer #: 61799
BELTRAN, MONICA



Subtotal for Job #1: 290.66

Job #2 - Warranty

COMPLAINT: CUSTOMER STATES DRIVER BLIND IN BEDROOM WILL NOT STAY UP

CAUSE: Will it up out of adjustment

CORRECTION: Adjusted the tension lines on both sides of the bedroom window, retested the blind to ensure that it would actually stay up completely, which it now stays up work is now complete.
.25HRS

Labor

Job #	Description	Total
2	BLIND ADJUST	38.00

Subtotal for Job #2: 38.00

Job #3 - External

COMPLAINT: CUSTOMER STATES REALIGN EQUALIZER BRACKETS / REFERENCE: 73638

CORRECTION: WILL ALIGN WHEN CUSTOMER PICKS UP UNIT

Labor

Job #	Description	Total
3	ADJUST EQUALIZER	N/C

Subtotal for Job #3: 0.00

Job #4 - External

COMPLAINT: REPLACE BREAKAWAY LANYARD WITH COIL TYPE

CAUSE: Damaged

CORRECTION: Removed old break away
Installed new break away cable (coil type)
Work complete Requesting

Labor

Job #	Description	Total
4	LANYARD	N/C

Subtotal for Job #4: 0.00

Parts Total:	5.66
Labour Total:	323.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	328.66

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.



Customer Signature : _____

Date: 24 Aug 2026

W/O: 73722
Promised Date: 17 JUL 26



Customer #: 61799
BELTRAN, MONICA



Customer Work
Order

