



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 67
Promise
Date:



CUSTOMER WORK ORDER

WO #: 67240

Customer: 39750 - FEHRENBACHER,
JON A. - 812-483-4449

Tag:

Author: BJW

Location: 1205 CHECK PREAUTH

Stock #: 10826

Stock Desc: 2022 TT FOREST RIVER
CHEROKEE 274BRB

Chassis #: 4X4TCKC27NX155487

Serial #: 4X4TCKC27NX155487

Mileage:

Licence:

Invoice #:

Date In: 26 APR 22

Promised: 30 APR 22

Date Sched:

Completed: 30 NOV 22

Warr. Date: 29 MAR 22

Job #1 - Warranty

COMPLAINT: THE REAR EXTERIOR DOOR GOING INTO THE BATHROOM WILL NOT CATCH WHEN CLOSING.

CAUSE: THE REAR EXTERIOR DOOR GOING INTO THE BATHROOM WILL NOT CATCH WHEN CLOSING.

unit is not here 6/28/22

CORRECTION: Checked operation of rear exterior door. When paddle handle is locked, the door can be opened from the outside without unlocking. Added washers behind latch plate to allow lock plunger to catch and lock. Then screen door hits latch and will not open or close. Removed washers and screen door opens and closes ok. But paddle handle will open from outside when locked. Complete door assembly needs replaced.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	0.00
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	150.00
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	0.00

Parts

Part #	Description	Qty	Price	Total
F100307275	ENTRY DOOR, SCREEN DOOR ONLY - 26" X 72" RH, BLACK FRAME / V000385559 (REPLACES V000630612)	1.00	114.34	114.34

Subtotal for Job #1: 264.34

Parts Total: 114.34
Labour Total: 150.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 264.34

Customer #:
39750

