



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O : 67248

CUSTOMER WORK ORDER

WO #: 67248 (Appointment Date: 27 APR 2022 - Time: 07:00am)

Customer: 1000 - BASDEN'S AMERICAN RV - Stock #: 10563
RV - Stock Desc: 2022 TT COACHMEN
Tag: CATALINA 192FQS
Author: P.HUNT Chassis #: 5ZT2CAHC6NK003063
Location: 0531 CHECK WORK Serial #: 5ZT2CAHC6NK003063
Mileage:
Licence:

Invoice #:
Date In: 26 APR 22
Promised:
Date Sched:
Completed: 25 MAY 22
Warr. Date: 18 NOV 21

Job #1 - Warranty

COMPLAINT: CHECK SLIDE SEALS, CAN SEE A GAP AT THE TOP FROM THE INSIDE ON THE FRONT OF THE SLIDE

CAUSE: BOTH INSIDE BULB SEALS AND TRACKS THAT THE SEALS GO ONTO ARE PULLED UP OVER THE TOP OF THE SLIDE ROOM AROUND THE MOTORS, OUTSIDE WIPER SEAL ON TOP OF SLIDE ISNT MOVING AND IS BUNCHED UP BECAUSE THE SLIDE ROOM IS TOO CLOSE TO THE TOP OF THE WALL. BULB SEAL ON OUTSIDE FRONT OF SLIDE ROOM IS ALSO DAMAGED. BEN IS TO CALL WARRANTY FOR FURTHER INSTRUCTION AND APPROVAL. 4/27/22

Other Services

| Code | Description | Qty | Price | Total |
|-----------------------------|---------------|------|-------|-------------|
| SS | SHOP SUPPLIES | 1.00 | 0.00 | 0.00 |
| Subtotal for Job #1: | | | | 0.00 |

Job #2 - Warranty

COMPLAINT: THE BULB SEAL ON THE TOP OUTSIDE REAR IS STARTING TO COME OFF AND DOES NOT LOOK RIGHT

CORRECTION: REMOVE INSIDE TRIM ON SLIDEROOM. REMOVE INSIDE SEAL. REMOVE OUTSIDE SEAL ON SLIDEROOM. CUT 3/4 " OOF THE TOP OF THE SLIDEROOM WALL. PUT ON NEW SEALS IN AND OUTSIDE OF SLIDEROOM ON TOP. FIX BULB SEAL INSIDE. PUT NEW BULB SEAL ON LEFT OF SLIDEROOM.

Labor

| Code | Description | Mechanic | Total |
|------|-----------------------------|----------|--------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | ZMS | 130.50 |
| Z990 | MISC LABOUR CODE (EXTERNAL) | BB | 823.50 |
| Z990 | MISC LABOUR CODE (EXTERNAL) | BB | 214.50 |
| Z990 | MISC LABOUR CODE (EXTERNAL) | BB | 51.00 |
| Z990 | MISC LABOUR CODE (EXTERNAL) | BB | 529.50 |
| Z990 | MISC LABOUR CODE (EXTERNAL) | BB | 51.00 |

Parts

| Part # | Description | Qty | Price | Total |
|---------|--------------------|------|--------|--------|
| 13-1066 | -3/4 Inch Width x | 1.00 | 158.56 | 158.56 |
| 13-1069 | 018-312-EKD 35' D- | 1.00 | 77.65 | 77.65 |

Subtotal for Job #2: 2,036.21



Customer #: 1000
BASDEN'S AMERICAN RV,



| | |
|--------------------------|-----------------|
| Parts Total: | 236.21 |
| Labour Total: | 1,800.00 |
| Sublet Total: | 0.00 |
| Extras Total: | 0.00 |
| WORK ORDER TOTAL: | 2,036.21 |

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 25 May 2022

Customer Work Order



Customer #: 1000
BASDEN'S AMERICAN RV,

