

Claim Response

Claim: C3077627

Non-Warranty Goodwill Adjustment

Last Modified by ambri

Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed warranty rate	Type	Date Of Purchase
C3077627	67264	4/28/2022	4/28/2022	4YDT28222K3105013		1194	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	150.00	0.00	SA21-414	11/15/2019

Deny code	Item number	Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
	446897	Hose - LP - 12" Pigtail	2.00	0.00	6.65	15.00	15.30	0.00	0.00	0.00	Approved
	102038	Regulator - LP - Auto Change	1.00	0.00	51.16	15.00	58.83	0.00	0.00	0.00	Approved

locally
Component Model: 6020 Component Serial Number: N 18 23

Deny code	Operation	Description	Srvc advisory	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	7141442B	Safety Advisory 21-414 Winn-Tec Complaint: RECALL ON LP REGULATOR Cause: RECALL Correction: TOOK OFF OLD PARTS AND INSTALLED NEW REGULATER AND 2 NEW HOSES HAD TO DRILL OUT BRACKET HOLES DID NOT LINE UP,CHECKED FOR LEAKS AND ALL IS GOOD. (Camco/locally)		0.50	0.50	75.00	0.00	1	0.50	Approved

Submitted parts & subLet 74.13
Submitted labor & subLet 75.00
Submitted freight: 0.00
Tax: 0.00
Total Submitted: 149.13

Approved parts & subLet 74.13
Approved labor & subLet 75.00
Approved freight: 0.00
Tax: 0.00
Total approved: 149.13