

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13970

Date In:	17 AUG 26	Author:	DMCGINLEY
Promised Date:	28 AUG 26	Stock No:	11381
:	:	Year:	2025
Customer Name:	1021 - FOREST RIVER	Manufacturer:	FOREST RIVER
Address:	21815 NETWORK PLACE	Brand:	FLAGSTAFF E-PRO
:	CHICAGO, IL	Model:	E20FBS
Postal/Zip:	60673-1218	Miles/Hrs:	0
Phone#(res):	219-534-3167	Exterior Color:	:
Phone#(bus):	219-534-3167	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	:
Purchased Date:	07 MAY 25	:	:
Delivery Date:	03 JUN 25	:	:
InService Date:	:	:	:
Serial#:	5ZT2FSKC5S3038611	:	:

Job # Description JOB INFORMATION Type Bill To

1 COMPLAINT: CUSTOMER STATES HE HAS NO POWER TO HIS W 1021 FORES
OUTLETS AND HIS GFI WILL NOT RESET.
BREAKERS ARENT TRIPPED AND INVERTER IS
FLIPPED ON. AC, REFER, ECT WORK.
CAUSE: Line wire on AC Out levernut inside of
inverter was cut too short and not
inserted completely into the connection
causing arcing and burning of the
connector. Levernut is melted and will
not open to receive fresh wire. Will
need replacement inverter.
CORRECTION: Bypassed inverter while waiting for
replacement.

Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total

1 DIAG DIAGNOSTICS MF W-1021 0.50 140.00 70.00
1 Z990 R&R Inverter W-1021 0.00 140.00 0.00

Job # Excode Description EXTRAS bill to Qty Price Total

1 SSE SHOP SUPPLIES - EXTERNAL W-1021 1.00 0.00 0.00

Continued on page 2

Work Order : 13970

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
W	1021	0.00	70.00	0.00	0.00	0.00	70.00
	Totals	0.00	70.00	0.00	0.00	0.00	70.00

&k2S
&k0S