

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13708

Date In:	24 JUN 26	Author:	DLUCAS
Promised Date:	01 JUL 26	Stock No:	11259
:	:	Year:	2025
Customer Name:	122926 - MCDONOUGH, MI	Manufacturer:	FOREST RIVER
Address:	1148 S. BUTTERCUP CT.	Brand:	PUMA DESTINATION
:	FRIENDSHIP, WI	Model:	402LFT
Postal/Zip:	53934	Miles/Hrs:	0
Phone#(res):	262-939-5796	Exterior Color:	
Phone#(bus):		Unit Type:	TT-TRAVEL TRAILER
Cell Phone:		License#:	
Email:	YMIKEJ@YAHOO.COM	Tag#:	DB - 7/10
Purchased Date:	21 JUN 25	:	:
Delivery Date:	28 JUN 25	:	:
InService Date:		:	:
Serial#:	4X4TPUS2XSP104319	:	:

Job #	Description	JOB INFORMATION	Type	Bill To
SC	CUSTOMER REQUESTS SERVICE CALL TO 1003 MOOR COURT		E	122926 MCDON
	ROME CALL CMR IF DOG IS THERE.			
1	COMPLAINT: CUSTOMER STATES AWNING BOTH SIDES ARE		W	1021 FORES
	JUTTED OUT AWNING IS BINDING UP AND			
	GETTING WORSE DOESNT COME IN ALL THE WAY			
	CAUSE: the awning fabric is stretched and tube			
	is sagging won't close on motor side			
	pics taken of tags need new awning			
	fabric and tube with lights			
	CORRECTION: Will need awning fabric with tubes and			
	lights REQUEST 2.0			
2	COMPLAINT: CUSTOMER STATES GUTTER STILL LEAKING		W	1021 FORES
	AFTER REPAIR			
	CAUSE: Couldn't do and sealants on gutter track			
	due to rainy and storms I'm assuming I			
	can do when fabric and awning tube			
	replacement			
	CORRECTION: Couldn't do at this time			
3	COMPLAINT: CUSTOMER STATES SHADE ON UPPER SMALL		W	1021 FORES
	WINDOW HAS PINHOLES			
	CAUSE: install a front motorized shade but			
	customer also found another shade above			
	tv with pin holes as well pics taken			
	CORRECTION: installed shade Request .5			
4	COMPLAINT: CUSTOMER STATES FENDER IS BROKE ON BOTH		W	1021 FORES
	SIDES OF TRAILER AND SCREWS POPPED OUT			
	CAUSE: pics and measurements taken both fender			
	skirts are cracked will need replacing			

Continued on page 2

Work Order : 13708

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
CORRECTION: needs two fender skirts door side and
off door side .... REQUEST 1.0
5 COMPLAINT: ANOTHER SHADE IN UNIT HAS PINHOLES          W    1021    FORES
*PICTURES IN LINE 3* AND NEEDS
REPLACEMENT
CAUSE:      SHADE HAS PINHOLES
CORRECTION: NEED NEW SHADE REQUEST .5

```

```

*****
Job # Part No   Description          PARTS          Bill to   Qty    Price    Total
*****
1      82204665  AWNING, 21' LED/BLACK SOLID W-1021      0    413.26    0.00
3      822090839  SHAD, MOTORIZED ROLLER, 42" W-1021      0    111.01    0.00
4      822014802  FENDERSKIRT, LARGE PUMA TAN W-1021      0     40.76    0.00
5      822090839  SHAD, MOTORIZED ROLLER, 42" W-1021      0    111.01    0.00

```

```

*****
Job# Lab Code Description          LABOUR    Mech Bill to   Hrs    Rate    Total
*****
1 Z992      MISC LABOUR CODE (WARR JS W-1021      0.50  140.00    70.00
2 Z992      MISC LABOUR CODE (WARR JS W-1021      0.50  140.00    70.00
3 Z992      MISC LABOUR CODE (WARR JS W-1021      0.50  140.00    70.00
4 Z992      MISC LABOUR CODE (WARR JS W-1021      0.50  140.00    70.00

```

```

*****
Job # Excode   Description          EXTRAS          bill to   Qty    Price    Total
*****
SC SSE        SHOP SUPPLIES - EXTERNAL E-122926  1.00    0.00    0.00

```

```

*****
Type Bill Id   Parts    Labour    Sublet    Extras    Tax    Total
*****
W    1021      0.00    280.00    0.00    0.00    0.00    280.00

Totals        0.00    280.00    0.00    0.00    0.00    280.00

```

&k2S
&k0S